

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |            | Listing Submitted   |            | 8/4/2020   |            | Area of state conducts work   |  |
|--|------------|---|------------|--|------------|---|--|
| <b>Advanced Environmental Services, Inc.</b><br>PO Box 38218<br>Greensboro, NC 27438 |            | <b>Phone</b> (336) 282-3586<br><b>Fax</b> (336) 282-3587<br><b>Website</b> <a href="http://advancedenvironmental.com">advancedenvironmental.com</a> |            |  |            | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring  |            |   |            | UST Equipment Service Contractors                |            |   |  |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:  | No         | Dispenser Meter Repair/Calibration:              | No         |   |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:  | No         | Leak Detection Equipment Installation Servicing: | No         |   |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:   | No         | Spill Bucket Installation Repair:                | No         |   |  |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:   | No         | UST Equipment Installation - Other:              | No         |   |  |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments):   | No         | UST Equipment Repair:                            | No         |   |  |
| Leak Detection Equipment Operability Check:  | No         | UST Internal Lining Inspections:  | No         | UST System Installation - Complete Systems:      | No         |   |  |
| Leak Detection Monitoring Services:  | No         | Other:  |            | UST Piping/Sump Installation:                    | No         |   |  |
| Line Tightness Testing:  | No         |   |            | UST System Removal:                              | <u>Yes</u> |   |  |
| <b>Environmental Service Firms</b>   |            |   |            | Other:   |            |   |  |
| Emergency Cleanup - Spill/Release:   | <u>Yes</u> | UST Compliance Consultants:   | No         |  |            |   |  |
| Environmental Engineer/Geologist - Site Checks:                                      | <u>Yes</u> | UST Equipment Verification:   | No         |  |            |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                                  | <u>Yes</u> | Waste Disposal and Treatment:   | <u>Yes</u> |  |            |   |  |
| Oil and Solvent Recycling:   | No         | Other:  |            |  |            |   |  |
| Soil and Water Testing Lab:  | No         |   |            |  |            |   |  |

  

| Company  |            | Listing Submitted   |            | 5/17/2021  |            | Area of state conducts work   |  |
|--|------------|---|------------|--|------------|---|--|
| <b>AES of Greenville LLC</b><br>141 S. Market Street<br>Washington, NC 27889 |            | <b>Phone</b> (252) 758-3311<br><b>Fax</b> (252) 481-5814<br><b>Website</b> <a href="http://www.aes-nc.com">www.aes-nc.com</a> |            |  |            | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring  |            |   |            | UST Equipment Service Contractors                |            |   |  |
| Automatic Line Leak Detector Testing:  | <u>Yes</u> | Overfill Prevention Equipment Operability Check:  | <u>Yes</u> | Dispenser Meter Repair/Calibration:              | No         |   |  |
| Containment Sump Testing:  | <u>Yes</u> | Statistical Inventory Reconciliation Services:  | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | No         |   |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:   | <u>Yes</u> | Spill Bucket Installation Repair:                | No         |   |  |
| Corrosion Protection System Repairs:   | <u>Yes</u> | Tank Tightness Testing:   | <u>Yes</u> | UST Equipment Installation - Other:              | No         |   |  |
| Corrosion Protection System Testing:   | <u>Yes</u> | UST Internal Inspections (Integrity Assessments):   | <u>Yes</u> | UST Equipment Repair:                            | No         |   |  |
| Leak Detection Equipment Operability Check:                                  | <u>Yes</u> | UST Internal Lining Inspections:  | <u>Yes</u> | UST System Installation - Complete Systems:      | No         |   |  |
| Leak Detection Monitoring Services:  | <u>Yes</u> | Other:  |            | UST Piping/Sump Installation:                    | No         |   |  |
| Line Tightness Testing:  | <u>Yes</u> |   |            | UST System Removal:                              | <u>Yes</u> |   |  |
| <b>Environmental Service Firms</b>   |            |   |            | Other:   |            |   |  |
| Emergency Cleanup - Spill/Release:   | No         | UST Compliance Consultants:   | <u>Yes</u> |  |            |   |  |
| Environmental Engineer/Geologist - Site Checks:                              | No         | UST Equipment Verification:   | <u>Yes</u> |  |            |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                          | No         | Waste Disposal and Treatment:   | No         |  |            |   |  |
| Oil and Solvent Recycling:   | No         | Other:  |            |  |            |   |  |
| Soil and Water Testing Lab:  | No         |   |            |  |            |   |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     | Listing Submitted                                 |     | 4/15/2021  |  | Area of state conducts work  |  |
|---|-----|---|-----|--|--|--|--|
| American UST Compliance Testing<br>180 BPW Club Rd. A-1<br>Carrboro, NC 27510 |     | Phone (919) 777-8543<br><br>Fax<br><br>Website    |     |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring   |     |   |     | UST Equipment Service Contractors                |  |  |  |
| Automatic Line Leak Detector Testing:   | Yes | Overfill Prevention Equipment Operability Check:  | Yes | Dispenser Meter Repair/Calibration:              |  | Yes  |  |
| Containment Sump Testing:   | Yes | Statistical Inventory Reconciliation Services:    | No  | Leak Detection Equipment Installation Servicing: |  | No   |  |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:               | Yes | Spill Bucket Installation Repair:                |  | Yes  |  |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:                           | Yes | UST Equipment Installation - Other:              |  | No   |  |
| Corrosion Protection System Testing:  | Yes | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair:                            |  | Yes  |  |
| Leak Detection Equipment Operability Check:                                   | Yes | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems:      |  | No   |  |
| Leak Detection Monitoring Services:   | No  | Other:  |     | UST Piping/Sump Installation:                    |  | No   |  |
| Line Tightness Testing:   | Yes |   |     | UST System Removal:                              |  | No   |  |
| Environmental Service Firms   |     |   |     | Other:   |  |  |  |
| Emergency Cleanup - Spill/Release:  | Yes | UST Compliance Consultants:                       | Yes |  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:                               | No  | UST Equipment Verification:                       | No  |  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                           | No  | Waste Disposal and Treatment:                     | No  |  |  |  |  |
| Oil and Solvent Recycling:  | No  | Other:  |     |  |  |  |  |
| Soil and Water Testing Lab:   | No  |   |     |  |  |  |  |

| Company  |     | Listing Submitted   |     | 5/17/2021  |  | Area of state conducts work  |  |
|--|-----|---|-----|--|--|--|--|
| Apex Engineering, PC<br>15850 Crabbs Branch Way<br>Suite 200<br>Rockville, Maryland 20855- |     | Phone (301) 417-0200<br><br>Fax (301) 975-0169<br><br>Website www.apexcos.com |     |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring  |     |   |     | UST Equipment Service Contractors                |  |  |  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:                              | No  | Dispenser Meter Repair/Calibration:              |  | No   |  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:                                | No  | Leak Detection Equipment Installation Servicing: |  | No   |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:   | No  | Spill Bucket Installation Repair:                |  | No   |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:   | No  | UST Equipment Installation - Other:              |  | No   |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):                             | No  | UST Equipment Repair:                            |  | No   |  |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:  | No  | UST System Installation - Complete Systems:      |  | No   |  |
| Leak Detection Monitoring Services:  | No  | Other:  |     | UST Piping/Sump Installation:                    |  | No   |  |
| Line Tightness Testing:  | No  |   |     | UST System Removal:                              |  | Yes  |  |
| Environmental Service Firms  |     |   |     | Other:   |  |  |  |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:   | Yes |  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:  | Yes | UST Equipment Verification:   | Yes |  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | Yes | Waste Disposal and Treatment:   | Yes |  |  |  |  |
| Oil and Solvent Recycling:   | Yes | Other:  |     |  |  |  |  |
| Soil and Water Testing Lab:  | Yes |   |     |  |  |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     | Listing Submitted   |     | 7/30/2020  |  | Area of state conducts work  |    |
|---|-----|---|-----|--|--|--|----|
| Blue Ridge Geological Services, Inc.<br>7356 Belmont Drive<br>Trinity, NC 27370 |     | Phone (336) 382-6849<br><br>Fax<br><br>Website <a href="http://www.blueridgegeo.com">www.blueridgegeo.com</a> |     |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |    |
| Compliance Testing and Monitoring   |     |   |     | UST Equipment Service Contractors                |  |  |    |
| Automatic Line Leak Detector Testing:   | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              |  |  | No |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:  | No  | Leak Detection Equipment Installation Servicing: |  |  | No |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:   | No  | Spill Bucket Installation Repair:                |  |  | No |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:   | Yes | UST Equipment Installation - Other:              |  |  | No |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments):   | No  | UST Equipment Repair:                            |  |  | No |
| Leak Detection Equipment Operability Check:                                     | No  | UST Internal Lining Inspections:  | No  | UST System Installation - Complete Systems:      |  |  | No |
| Leak Detection Monitoring Services:   | No  | Other:  |     | UST Piping/Sump Installation:                    |  |  | No |
| Line Tightness Testing:   | Yes |   |     | UST System Removal:                              |  |  | No |
| Environmental Service Firms   |     |   |     | Other:   |  |  |    |
| Emergency Cleanup - Spill/Release:  | Yes | UST Compliance Consultants:   | Yes |  |  |  |    |
| Environmental Engineer/Geologist - Site Checks:                                 | Yes | UST Equipment Verification:   | No  |  |  |  |    |
| Environmental Engineer/Geologist Soil and GW Cleanu                             | Yes | Waste Disposal and Treatment:   | No  |  |  |  |    |
| Oil and Solvent Recycling:  | No  | Other:  |     |  |  |  |    |
| Soil and Water Testing Lab:   | Yes |   |     |  |  |  |    |

| Company   |            | Listing Submitted  |            | 2/1/2021   |   | Area of state conducts work |  |
|---|------------|--|------------|--|---|-----------------------------|--|
| <b>Buckeye Elm Contracting</b><br>PO Box 1026<br>Mocksville, NC 27028 |            | <b>Phone</b> (888) 315-8663<br><b>Fax</b><br><b>Website</b> <a href="http://www.buckeye-elm.com">www.buckeye-elm.com</a> |            |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |                             |  |
| Compliance Testing and Monitoring                                     |            |  |            | UST Equipment Service Contractors                |   |                             |  |
| Automatic Line Leak Detector Testing:                                 | No         | Overfill Prevention Equipment Operability Check:   | No         | Dispenser Meter Repair/Calibration:              | No  |                             |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:   | No         | Leak Detection Equipment Installation Servicing: | No  |                             |  |
| Corrosion Protection Design Experts:                                  | No         | Spill Prevention Equipment Testing:  | No         | Spill Bucket Installation Repair:                | No  |                             |  |
| Corrosion Protection System Repairs:                                  | No         | Tank Tightness Testing:  | No         | UST Equipment Installation - Other:              | No  |                             |  |
| Corrosion Protection System Testing:                                  | No         | UST Internal Inspections (Integrity Assessments):  | No         | UST Equipment Repair:                            | No  |                             |  |
| Leak Detection Equipment Operability Check:                           | No         | UST Internal Lining Inspections:   | No         | UST System Installation - Complete Systems:      | No  |                             |  |
| Leak Detection Monitoring Services:                                   | No         | Other:   |            | UST Piping/Sump Installation:                    | No  |                             |  |
| Line Tightness Testing:   | No         |  |            | UST System Removal:                              | <u>Yes</u>  |                             |  |
| Environmental Service Firms   |            |  |            | Other:   |   |                             |  |
| Emergency Cleanup - Spill/Release:                                    | <u>Yes</u> | UST Compliance Consultants:  | No         |  |   |                             |  |
| Environmental Engineer/Geologist - Site Checks:                       | No         | UST Equipment Verification:  | No         |  |   |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                   | No         | Waste Disposal and Treatment:  | <u>Yes</u> |  |   |                             |  |
| Oil and Solvent Recycling:  | <u>Yes</u> | Other:   |            |  |   |                             |  |
| Soil and Water Testing Lab:   | No         |  |            |  |   |                             |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     |   | Listing Submitted  |  | 1/10/2022  |    | Area of state conducts work |  |
|---|-----|---|--|--|--|----|-----------------------------|--|
| Bunnell-Lammons Engineering, Inc.<br>130 Oval Road<br>Arden, NC 28704 |     |   | Phone (828) 277-0100<br>Fax (828) 277-0110<br>Website <a href="http://www.blecorp.com">www.blecorp.com</a> |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |    |                             |  |
| Compliance Testing and Monitoring                                     |     |   |  |  | UST Equipment Service Contractors  |    |                             |  |
| Automatic Line Leak Detector Testing:                                 | Yes | Overfill Prevention Equipment Operability Check:  | Yes  | Dispenser Meter Repair/Calibration:              |  | No |                             |  |
| Containment Sump Testing:   | Yes | Statistical Inventory Reconciliation Services:    | Yes  | Leak Detection Equipment Installation Servicing: |  | No |                             |  |
| Corrosion Protection Design Experts:                                  | Yes | Spill Prevention Equipment Testing:               | Yes  | Spill Bucket Installation Repair:                |  | No |                             |  |
| Corrosion Protection System Repairs:                                  | Yes | Tank Tightness Testing:                           | Yes  | UST Equipment Installation - Other:              |  | No |                             |  |
| Corrosion Protection System Testing:                                  | Yes | UST Internal Inspections (Integrity Assessments): | Yes  | UST Equipment Repair:                            |  | No |                             |  |
| Leak Detection Equipment Operability Check:                           | Yes | UST Internal Lining Inspections:                  | Yes  | UST System Installation - Complete Systems:      |  | No |                             |  |
| Leak Detection Monitoring Services:                                   | Yes | Other:  |  | UST Piping/Sump Installation:                    |  | No |                             |  |
| Line Tightness Testing:   | Yes |   |  | UST System Removal:                              |  | No |                             |  |
| Environmental Service Firms   |     |   |  |  | Other:   |    |                             |  |
| Emergency Cleanup - Spill/Release:                                    | No  | UST Compliance Consultants:                       | Yes  |  |  |    |                             |  |
| Environmental Engineer/Geologist - Site Checks:                       | Yes | UST Equipment Verification:                       | Yes  |  |  |    |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                   | Yes | Waste Disposal and Treatment:                     | Yes  |  |  |    |                             |  |
| Oil and Solvent Recycling:  | No  | Other:  |  | Trust Fund Projects                              |  |    |                             |  |
| Soil and Water Testing Lab:   | No  |   |  |  |  |    |                             |  |

| Company  |     |   | Listing Submitted   |  | 5/18/2022  |    | Area of state conducts work |  |
|--|-----|---|---|--|--|----|-----------------------------|--|
| Cape Fear Engineering, Inc.<br>151 Poole Road<br>Suite 100<br>Leland, NC 28451 |     |   | Phone (910) 383-1044<br>Fax<br>Website <a href="http://www.capefearengineering.com">www.capefearengineering.com</a> |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): No<br>Mountains (West of I-77): No |    |                             |  |
| Compliance Testing and Monitoring  |     |   |   |  | UST Equipment Service Contractors  |    |                             |  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              |  | No |                             |  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:    | No  | Leak Detection Equipment Installation Servicing: |  | No |                             |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:               | No  | Spill Bucket Installation Repair:                |  | No |                             |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:                           | No  | UST Equipment Installation - Other:              |  | No |                             |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair:                            |  | No |                             |  |
| Leak Detection Equipment Operability Check:                                    | No  | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems:      |  | No |                             |  |
| Leak Detection Monitoring Services:  | No  | Other:  |   | UST Piping/Sump Installation:                    |  | No |                             |  |
| Line Tightness Testing:  | No  |   |   | UST System Removal:                              |  | No |                             |  |
| Environmental Service Firms  |     |   |   |  | Other:   |    |                             |  |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                       | Yes   |  |  |    |                             |  |
| Environmental Engineer/Geologist - Site Checks:                                | Yes | UST Equipment Verification:                       | No  |  |  |    |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                            | Yes | Waste Disposal and Treatment:                     | Yes   |  |  |    |                             |  |
| Oil and Solvent Recycling:   | No  | Other:  |   |  |  |    |                             |  |
| Soil and Water Testing Lab:  | No  |   |   |  |  |    |                             |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |            | Listing Submitted   |            | 5/18/2022  |  | Area of state conducts work  |  |
|--|------------|---|------------|--|--|--|--|
| Cape Fear Engineering, Inc.<br>151 Poole Road<br>Suite 100<br>Leland, NC 28451 |            | Phone (910) 383-1044<br><br>Fax<br><br>Website <a href="http://www.capefearengineering.com">www.capefearengineering.com</a> |            |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): No<br>Mountains (West of I-77): No |  |
| Compliance Testing and Monitoring  |            |   |            | UST Equipment Service Contractors                |  |  |  |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:  | No         | Dispenser Meter Repair/Calibration:              |  | No   |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:  | No         | Leak Detection Equipment Installation Servicing: |  | No   |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:   | No         | Spill Bucket Installation Repair:                |  | No   |  |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:   | No         | UST Equipment Installation - Other:              |  | No   |  |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments):   | No         | UST Equipment Repair:                            |  | No   |  |
| Leak Detection Equipment Operability Check:                                    | No         | UST Internal Lining Inspections:  | No         | UST System Installation - Complete Systems:      |  | No   |  |
| Leak Detection Monitoring Services:  | No         | Other:  |            | UST Piping/Sump Installation:                    |  | No   |  |
| Line Tightness Testing:  | No         |   |            | UST System Removal:                              |  | No   |  |
| Environmental Service Firms  |            |   |            | Other:   |  |  |  |
| Emergency Cleanup - Spill/Release:   | No         | UST Compliance Consultants:   | <u>Yes</u> |  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:                                | <u>Yes</u> | UST Equipment Verification:   | No         |  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                            | <u>Yes</u> | Waste Disposal and Treatment:   | <u>Yes</u> |  |  |  |  |
| Oil and Solvent Recycling:   | No         | Other:  |            |  |  |  |  |
| Soil and Water Testing Lab:  | No         |   |            |  |  |  |  |

| Company   |            | Listing Submitted   |            | 1/3/2020   |  | Area of state conducts work   |  |
|---|------------|---|------------|--|--|---|--|
| CATLIN Engineers and Scientists<br>220 Old Dairy Road<br>Wilmington, NC 28405 |            | Phone (910) 452-5861<br><br>Fax<br><br>Website <a href="http://www.CatlinUSA.com">www.CatlinUSA.com</a> |            |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): No |  |
| Compliance Testing and Monitoring   |            |   |            | UST Equipment Service Contractors                |  |   |  |
| Automatic Line Leak Detector Testing:   | No         | Overfill Prevention Equipment Operability Check:  | No         | Dispenser Meter Repair/Calibration:              |  | No  |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:  | No         | Leak Detection Equipment Installation Servicing: |  | No  |  |
| Corrosion Protection Design Experts:  | No         | Spill Prevention Equipment Testing:   | No         | Spill Bucket Installation Repair:                |  | No  |  |
| Corrosion Protection System Repairs:  | No         | Tank Tightness Testing:   | No         | UST Equipment Installation - Other:              |  | No  |  |
| Corrosion Protection System Testing:  | No         | UST Internal Inspections (Integrity Assessments):   | No         | UST Equipment Repair:                            |  | No  |  |
| Leak Detection Equipment Operability Check:                                   | No         | UST Internal Lining Inspections:  | No         | UST System Installation - Complete Systems:      |  | No  |  |
| Leak Detection Monitoring Services:   | No         | Other:  |            | UST Piping/Sump Installation:                    |  | No  |  |
| Line Tightness Testing:   | No         |   |            | UST System Removal:                              |  | <u>Yes</u>  |  |
| Environmental Service Firms   |            |   |            | Other:   |  |   |  |
| Emergency Cleanup - Spill/Release:  | <u>Yes</u> | UST Compliance Consultants:   | <u>Yes</u> |  |  |   |  |
| Environmental Engineer/Geologist - Site Checks:                               | <u>Yes</u> | UST Equipment Verification:   | No         |  |  |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                           | <u>Yes</u> | Waste Disposal and Treatment:   | <u>Yes</u> |  |  |   |  |
| Oil and Solvent Recycling:  | No         | Other:  |            |  |  |   |  |
| Soil and Water Testing Lab:   | <u>Yes</u> |   |            |  |  |   |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     |  |     | Listing Submitted                                | 8/18/2020 | Area of state conducts work |  |
|--|-----|--|-----|--|-----------|-----------------------------|--|
| Charles Broadfoot & Associates, Inc.<br>PO Box 53730<br>1827 Morganton Rd.<br>Fayetteville, NC 28305 |     | Phone (910) 574-4748<br><br>Fax 253-681-05<br><br>Website <a href="http://www.ustcomonline.com">www.ustcomonline.com</a> |     |  |           |                             | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring  |     |  |     | UST Equipment Service Contractors                |           |                             |  |
| Automatic Line Leak Detector Testing:  | Off | Overfill Prevention Equipment Operability Check:   | Off | Dispenser Meter Repair/Calibration:              |           | Off                         |  |
| Containment Sump Testing:  | Off | Statistical Inventory Reconciliation Services:   | Off | Leak Detection Equipment Installation Servicing: |           | Off                         |  |
| Corrosion Protection Design Experts:   | Off | Spill Prevention Equipment Testing:  | Off | Spill Bucket Installation Repair:                |           | Off                         |  |
| Corrosion Protection System Repairs:   | Off | Tank Tightness Testing:  | Off | UST Equipment Installation - Other:              |           | Off                         |  |
| Corrosion Protection System Testing:   | Off | UST Internal Inspections (Integrity Assessments):  | Off | UST Equipment Repair:                            |           | Off                         |  |
| Leak Detection Equipment Operability Check:  | Off | UST Internal Lining Inspections:   | Off | UST System Installation - Complete Systems:      |           | Off                         |  |
| Leak Detection Monitoring Services:  | Off | Other:   |     | UST Piping/Sump Installation:                    |           | Off                         |  |
| Line Tightness Testing:  | Off |  |     | UST System Removal:                              |           | Off                         |  |
| Environmental Service Firms  |     |  |     | Other:   |           |                             |  |
| Emergency Cleanup - Spill/Release:   | Off | UST Compliance Consultants:  | Yes |  |           |                             |  |
| Environmental Engineer/Geologist - Site Checks:  | Off | UST Equipment Verification:  | Off |  |           |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | Off | Waste Disposal and Treatment:  | Off |  |           |                             |  |
| Oil and Solvent Recycling:   | Off | Other:   |     |  |           |                             |  |
| Soil and Water Testing Lab:  | Off |  |     |  |           |                             |  |

| Company  |     |   |     | Listing Submitted                                | 5/26/2021 | Area of state conducts work |   |
|--|-----|---|-----|--|-----------|-----------------------------|---|
| Christopher Dunlap, P.G.<br>166 Michigan Avenue<br>Asheville, NC 28806 |     | Phone (828) 505-6301<br><br>Fax<br><br>Website    |     |  |           |                             | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |
| Compliance Testing and Monitoring                                      |     |   |     | UST Equipment Service Contractors                |           |                             |   |
| Automatic Line Leak Detector Testing:                                  | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              |           | No                          |   |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:    | No  | Leak Detection Equipment Installation Servicing: |           | No                          |   |
| Corrosion Protection Design Experts:                                   | No  | Spill Prevention Equipment Testing:               | No  | Spill Bucket Installation Repair:                |           | No                          |   |
| Corrosion Protection System Repairs:                                   | No  | Tank Tightness Testing:                           | No  | UST Equipment Installation - Other:              |           | No                          |   |
| Corrosion Protection System Testing:                                   | No  | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair:                            |           | No                          |   |
| Leak Detection Equipment Operability Check:                            | No  | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems:      |           | No                          |   |
| Leak Detection Monitoring Services:                                    | No  | Other:  |     | UST Piping/Sump Installation:                    |           | No                          |   |
| Line Tightness Testing:  | No  |   |     | UST System Removal:                              |           | No                          |   |
| Environmental Service Firms  |     |   |     | Other:   |           |                             |   |
| Emergency Cleanup - Spill/Release:                                     | No  | UST Compliance Consultants:                       | Yes |  |           |                             |   |
| Environmental Engineer/Geologist - Site Checks:                        | Yes | UST Equipment Verification:                       | No  |  |           |                             |   |
| Environmental Engineer/Geologist Soil and GW Cleanu                    | Yes | Waste Disposal and Treatment:                     | No  |  |           |                             |   |
| Oil and Solvent Recycling:   | No  | Other:  |     |  |           |                             |   |
| Soil and Water Testing Lab:  | No  |   |     |  |           |                             |   |



## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     | Listing Submitted  |     | 6/17/2020  |    | Area of state conducts work  |  |
|--|-----|--|-----|--|----|--|--|
| Clark Group dba Clark Environmental Services, PC<br>P.O. Box 10136<br>Wilmington, NC 28404 |     | Phone (910) 392-5555<br>Fax (910) 392-5552<br>Website <a href="http://www.clarkgroup.us">www.clarkgroup.us</a> |     |  |    | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring  |     |  |     | UST Equipment Service Contractors                |    |  |  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:   | No  | Dispenser Meter Repair/Calibration:              | No |  |  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:   | No  | Leak Detection Equipment Installation Servicing: | No |  |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:  | No  | Spill Bucket Installation Repair:                | No |  |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:  | No  | UST Equipment Installation - Other:              | No |  |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):  | No  | UST Equipment Repair:                            | No |  |  |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:   | No  | UST System Installation - Complete Systems:      | No |  |  |
| Leak Detection Monitoring Services:  | No  | Other:   |     | UST Piping/Sump Installation:                    | No |  |  |
| Line Tightness Testing:  | No  |  |     | UST System Removal:                              | No |  |  |
| Environmental Service Firms  |     |  |     | Other:   |    |  |  |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:  | Yes |  |    |  |  |
| Environmental Engineer/Geologist - Site Checks:  | Yes | UST Equipment Verification:  | Yes |  |    |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | Yes | Waste Disposal and Treatment:  | Yes |  |    |  |  |
| Oil and Solvent Recycling:   | No  | Other:   |     |  |    |  |  |
| Soil and Water Testing Lab:  | No  |  |     |  |    |  |  |

| Company   |     | Listing Submitted  |     | 5/14/2021  |     | Area of state conducts work  |  |
|---|-----|--|-----|--|-----|--|--|
| Cobb Environmental & Technical Services, Inc.<br>P. O. Box 1602, Tupelo, MS 38802<br>871 South Green Street<br>Tupelo, MS 38804 |     | Phone (662) 841-0995<br>Fax (662) 841-0810<br>Website <a href="http://www.cobbenv.com">www.cobbenv.com</a> |     |  |     | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring   |     |  |     | UST Equipment Service Contractors                |     |  |  |
| Automatic Line Leak Detector Testing:   | Yes | Overfill Prevention Equipment Operability Check:   | Yes | Dispenser Meter Repair/Calibration:              | Yes |  |  |
| Containment Sump Testing:   | Yes | Statistical Inventory Reconciliation Services:   | No  | Leak Detection Equipment Installation Servicing: | Yes |  |  |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:  | Yes | Spill Bucket Installation Repair:                | Yes |  |  |
| Corrosion Protection System Repairs:  | Yes | Tank Tightness Testing:  | No  | UST Equipment Installation - Other:              | Yes |  |  |
| Corrosion Protection System Testing:  | Yes | UST Internal Inspections (Integrity Assessments):  | No  | UST Equipment Repair:                            | Yes |  |  |
| Leak Detection Equipment Operability Check:   | Yes | UST Internal Lining Inspections:   | No  | UST System Installation - Complete Systems:      | Yes |  |  |
| Leak Detection Monitoring Services:   | Yes | Other:   |     | UST Piping/Sump Installation:                    | Yes |  |  |
| Line Tightness Testing:   | No  |  |     | UST System Removal:                              | Yes |  |  |
| Environmental Service Firms   |     |  |     | Other:   |     |  |  |
| Emergency Cleanup - Spill/Release:  | No  | UST Compliance Consultants:  | Yes |  |     |  |  |
| Environmental Engineer/Geologist - Site Checks:   | No  | UST Equipment Verification:  | Yes |  |     |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | No  | Waste Disposal and Treatment:  | No  |  |     |  |  |
| Oil and Solvent Recycling:  | No  | Other:   |     |  |     |  |  |
| Soil and Water Testing Lab:   | No  |  |     |  |     |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |            |  |                           | Listing Submitted                                | 1/20/2022 | Area of state conducts work  |  |
|--|------------|--|---------------------------|--|-----------|--|--|
| <b>COHESION, INC</b><br>5216 YATES MILL POND RD<br>RALEIGH, NC 27606 |            | <b>Phone</b> (919) 233-8626<br><b>Fax</b><br><b>Website</b> <a href="http://WWW.COHESION-INC.COM">WWW.COHESION-INC.COM</a> |                           |  |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No |  |
| Compliance Testing and Monitoring                                    |            |  |                           |  |           | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:                                | No         | Overfill Prevention Equipment Operability Check:   | No                        | Dispenser Meter Repair/Calibration:              |           | No   |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:   | No                        | Leak Detection Equipment Installation Servicing: |           | No   |  |
| Corrosion Protection Design Experts:                                 | No         | Spill Prevention Equipment Testing:  | No                        | Spill Bucket Installation Repair:                |           | No   |  |
| Corrosion Protection System Repairs:                                 | No         | Tank Tightness Testing:  | No                        | UST Equipment Installation - Other:              |           | No   |  |
| Corrosion Protection System Testing:                                 | No         | UST Internal Inspections (Integrity Assessments):  | No                        | UST Equipment Repair:                            |           | No   |  |
| Leak Detection Equipment Operability Check:                          | No         | UST Internal Lining Inspections:   | No                        | UST System Installation - Complete Systems:      |           | No   |  |
| Leak Detection Monitoring Services:                                  | No         | Other:   |                           | UST Piping/Sump Installation:                    |           | No   |  |
| Line Tightness Testing:  | No         |  |                           | UST System Removal:                              |           | <u>Yes</u>   |  |
| Environmental Service Firms  |            |  |                           |  |           | Other:   |  |
| Emergency Cleanup - Spill/Release:                                   | <u>Yes</u> | UST Compliance Consultants:  | <u>Yes</u>                |  |           |  |  |
| Environmental Engineer/Geologist - Site Checks:                      | No         | UST Equipment Verification:  | No                        |  |           |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                  | No         | Waste Disposal and Treatment:  | No                        |  |           |  |  |
| Oil and Solvent Recycling:   | No         | Other:   | QED MOBILE LAB TPH - SOIL |  |           |  |  |
| Soil and Water Testing Lab:  | <u>Yes</u> |  |                           |  |           |  |  |

| Company  |            |   |            | Listing Submitted                                | 12/30/2021 | Area of state conducts work   |  |
|--|------------|---|------------|--|------------|---|--|
| <b>Crompco, LLC</b><br>1815 Gallagher Road<br>Plymouth Meeting, PA 19462 |            | <b>Phone</b> (610) 278-7203<br><b>Fax</b> (610) 278-7621<br><b>Website</b> <a href="http://www.crompco.com">www.crompco.com</a> |            |  |            | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring  |            |   |            |  |            | UST Equipment Service Contractors   |  |
| Automatic Line Leak Detector Testing:                                    | <u>Yes</u> | Overfill Prevention Equipment Operability Check:  | <u>Yes</u> | Dispenser Meter Repair/Calibration:              |            | <u>Yes</u>  |  |
| Containment Sump Testing:  | <u>Yes</u> | Statistical Inventory Reconciliation Services:  | <u>Yes</u> | Leak Detection Equipment Installation Servicing: |            | No  |  |
| Corrosion Protection Design Experts:                                     | No         | Spill Prevention Equipment Testing:   | <u>Yes</u> | Spill Bucket Installation Repair:                |            | No  |  |
| Corrosion Protection System Repairs:                                     | No         | Tank Tightness Testing:   | <u>Yes</u> | UST Equipment Installation - Other:              |            | <u>Yes</u>  |  |
| Corrosion Protection System Testing:                                     | <u>Yes</u> | UST Internal Inspections (Integrity Assessments):   | No         | UST Equipment Repair:                            |            | <u>Yes</u>  |  |
| Leak Detection Equipment Operability Check:                              | <u>Yes</u> | UST Internal Lining Inspections:  | No         | UST System Installation - Complete Systems:      |            | No  |  |
| Leak Detection Monitoring Services:                                      | <u>Yes</u> | Other:  |            | UST Piping/Sump Installation:                    |            | No  |  |
| Line Tightness Testing:  | <u>Yes</u> |   |            | UST System Removal:                              |            | No  |  |
| Environmental Service Firms  |            |   |            |  |            | Other:  |  |
| Emergency Cleanup - Spill/Release:                                       | No         | UST Compliance Consultants:   | <u>Yes</u> |  |            |   |  |
| Environmental Engineer/Geologist - Site Checks:                          | No         | UST Equipment Verification:   | <u>Yes</u> |  |            |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                      | No         | Waste Disposal and Treatment:   | No         |  |            |   |  |
| Oil and Solvent Recycling:   | No         | Other:  |            |  |            |   |  |
| Soil and Water Testing Lab:  | No         |   |            |  |            |   |  |



## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     | Listing Submitted   |                       | 9/28/2022  |     | Area of state conducts work  |  |
|---|-----|---|-----------------------|--|-----|--|--|
| D. H. Griffin Wrecking Company<br>4716 Hilltop Road<br>Greensboro, NC 27407 |     | Phone (336) 214-9012<br><br>Fax<br><br>Website <a href="http://www.dhgriffin.com">www.dhgriffin.com</a> |                       |  |     | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring   |     |   |                       | UST Equipment Service Contractors                |     |  |  |
| Automatic Line Leak Detector Testing:                                       | No  | Overfill Prevention Equipment Operability Check:  | No                    | Dispenser Meter Repair/Calibration:              | No  |  |  |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:  | No                    | Leak Detection Equipment Installation Servicing: | No  |  |  |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:   | No                    | Spill Bucket Installation Repair:                | No  |  |  |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:   | No                    | UST Equipment Installation - Other:              | No  |  |  |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments):   | No                    | UST Equipment Repair:                            | No  |  |  |
| Leak Detection Equipment Operability Check:                                 | No  | UST Internal Lining Inspections:  | No                    | UST System Installation - Complete Systems:      | No  |  |  |
| Leak Detection Monitoring Services:   | No  | Other:  |                       | UST Piping/Sump Installation:                    | No  |  |  |
| Line Tightness Testing:   | No  |   |                       | UST System Removal:                              | Yes |  |  |
| Environmental Service Firms   |     |   |                       | Other:   |     |  |  |
| Emergency Cleanup - Spill/Release:  | Yes | UST Compliance Consultants:   | No                    |  |     |  |  |
| Environmental Engineer/Geologist - Site Checks:                             | No  | UST Equipment Verification:   | No                    |  |     |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                         | No  | Waste Disposal and Treatment:   | Yes                   |  |     |  |  |
| Oil and Solvent Recycling:  | Yes | Other:  | Vacuum Truck Services |  |     |  |  |
| Soil and Water Testing Lab:   | No  |   |                       |  |     |  |  |

| Company  |     | Listing Submitted   |     | 5/26/2020  |     | Area of state conducts work   |  |
|--|-----|---|-----|--|-----|---|--|
| East Coast Environmental PA<br>3815 Junction Boulevard<br>Raleigh , NC 27603 |     | Phone (919) 772-0268<br><br>Fax<br><br>Website <a href="http://eastcoastenv.com">eastcoastenv.com</a> |     |  |     | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): No |  |
| Compliance Testing and Monitoring  |     |   |     | UST Equipment Service Contractors                |     |   |  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              | Yes |   |  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:  | No  | Leak Detection Equipment Installation Servicing: | Yes |   |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:   | No  | Spill Bucket Installation Repair:                | Yes |   |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:   | No  | UST Equipment Installation - Other:              | Yes |   |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):   | No  | UST Equipment Repair:                            | Yes |   |  |
| Leak Detection Equipment Operability Check:                                  | No  | UST Internal Lining Inspections:  | No  | UST System Installation - Complete Systems:      | Yes |   |  |
| Leak Detection Monitoring Services:  | No  | Other:  |     | UST Piping/Sump Installation:                    | Yes |   |  |
| Line Tightness Testing:  | No  |   |     | UST System Removal:                              | Yes |   |  |
| Environmental Service Firms  |     |   |     | Other:   |     |   |  |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:   | Yes |  |     |   |  |
| Environmental Engineer/Geologist - Site Checks:                              | Yes | UST Equipment Verification:   | Yes |  |     |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                          | Yes | Waste Disposal and Treatment:   | No  |  |     |   |  |
| Oil and Solvent Recycling:   | No  | Other:  |     |  |     |   |  |
| Soil and Water Testing Lab:  | No  |   |     |  |     |   |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |            | Listing Submitted  |            | 2/1/2021   |  | Area of state conducts work  |  |
|---|------------|--|------------|--|--|--|--|
| <b>EHC Environmental</b><br>207 West Fourth Avenue<br>Red Springs, NC 28377 |            | <b>Phone</b> (910) 843-4456<br><b>Fax</b> (910) 843-5376<br><b>Website</b> |            |  |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> No |  |
| Compliance Testing and Monitoring   |            |  |            | UST Equipment Service Contractors                |  |  |  |
| Automatic Line Leak Detector Testing:                                       | No         | Overfill Prevention Equipment Operability Check:                           | No         | Dispenser Meter Repair/Calibration:              |  | No   |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:                             | No         | Leak Detection Equipment Installation Servicing: |  | No   |  |
| Corrosion Protection Design Experts:  | No         | Spill Prevention Equipment Testing:  | No         | Spill Bucket Installation Repair:                |  | No   |  |
| Corrosion Protection System Repairs:  | No         | Tank Tightness Testing:  | No         | UST Equipment Installation - Other:              |  | No   |  |
| Corrosion Protection System Testing:  | No         | UST Internal Inspections (Integrity Assessments):                          | No         | UST Equipment Repair:                            |  | No   |  |
| Leak Detection Equipment Operability Check:                                 | No         | UST Internal Lining Inspections:   | No         | UST System Installation - Complete Systems:      |  | No   |  |
| Leak Detection Monitoring Services:   | No         | Other:   |            | UST Piping/Sump Installation:                    |  | No   |  |
| Line Tightness Testing:   | No         |  |            | UST System Removal:                              |  | <u>Yes</u>   |  |
| Environmental Service Firms   |            |  |            | Other:   |  |  |  |
| Emergency Cleanup - Spill/Release:  | <u>Yes</u> | UST Compliance Consultants:  | No         |  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:                             | No         | UST Equipment Verification:  | No         |  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                         | No         | Waste Disposal and Treatment:  | <u>Yes</u> |  |  |  |  |
| Oil and Solvent Recycling:  | <u>Yes</u> | Other:  abandonmentments, Phase I ESA's, Landfarm Soil Disposal            |            |  |  |  |  |
| Soil and Water Testing Lab:   | No         |  |            |  |  |  |  |

| Company  |            | Listing Submitted                                 |                                    | 7/30/2020  |  | Area of state conducts work  |  |
|--|------------|---|------------------------------------|--|--|--|--|
| Environmental Contracting & Consulting Services, P<br>10 3rd Avenue<br>Southern Shores, NC 27949 |            | Phone (757) 912-2276<br><br>Fax<br><br>Website    |                                    |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): No<br>Mountains (West of I-77): No |  |
| Compliance Testing and Monitoring  |            |   |                                    | UST Equipment Service Contractors                |  |  |  |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:  | No                                 | Dispenser Meter Repair/Calibration:              |  | No   |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:    | No                                 | Leak Detection Equipment Installation Servicing: |  | No   |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:               | No                                 | Spill Bucket Installation Repair:                |  | No   |  |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:                           | No                                 | UST Equipment Installation - Other:              |  | No   |  |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments): | No                                 | UST Equipment Repair:                            |  | No   |  |
| Leak Detection Equipment Operability Check:  | No         | UST Internal Lining Inspections:                  | No                                 | UST System Installation - Complete Systems:      |  | No   |  |
| Leak Detection Monitoring Services:  | No         | Other:  |                                    | UST Piping/Sump Installation:                    |  | No   |  |
| Line Tightness Testing:  | No         |   |                                    | UST System Removal:                              |  | <u>Yes</u>   |  |
| Environmental Service Firms  |            |   |                                    | Other:   |  |  |  |
| Emergency Cleanup - Spill/Release:   | <u>Yes</u> | UST Compliance Consultants:                       | <u>Yes</u>                         |  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:  | <u>Yes</u> | UST Equipment Verification:                       | <u>Yes</u>                         |  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | <u>Yes</u> | Waste Disposal and Treatment:                     | <u>Yes</u>                         |  |  |  |  |
| Oil and Solvent Recycling:   | <u>Yes</u> | Other:  | tank removals and in-situ closures |  |  |  |  |
| Soil and Water Testing Lab:  | <u>Yes</u> |   |                                    |  |  |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |            | Listing Submitted   | 8/4/2020   | Area of state conducts work   |            |
|---|------------|---|------------|---|------------|
| <b>Environmental Laboratories, Inc</b><br>PO Box 1729<br>Travelers Rest, SC 29609 |            | <b>Phone</b> (864) 370-0637<br><b>Fax</b> (864) 752-0948<br><b>Website</b> <a href="http://www.elabsinc.net">www.elabsinc.net</a> |            | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |            |
| Compliance Testing and Monitoring   |            |   |            | UST Equipment Service Contractors   |            |
| Automatic Line Leak Detector Testing:   | <u>Yes</u> | Overfill Prevention Equipment Operability Check:  | <u>Yes</u> | Dispenser Meter Repair/Calibration:   | <u>Yes</u> |
| Containment Sump Testing:   | <u>Yes</u> | Statistical Inventory Reconciliation Services:  | No         | Leak Detection Equipment Installation Servicing:  | <u>Yes</u> |
| Corrosion Protection Design Experts:  | No         | Spill Prevention Equipment Testing:   | <u>Yes</u> | Spill Bucket Installation Repair:   | <u>Yes</u> |
| Corrosion Protection System Repairs:  | <u>Yes</u> | Tank Tightness Testing:   | <u>Yes</u> | UST Equipment Installation - Other:   | <u>Yes</u> |
| Corrosion Protection System Testing:  | <u>Yes</u> | UST Internal Inspections (Integrity Assessments):   | <u>Yes</u> | UST Equipment Repair:   | <u>Yes</u> |
| Leak Detection Equipment Operability Check:                                       | <u>Yes</u> | UST Internal Lining Inspections:  | <u>Yes</u> | UST System Installation - Complete Systems:   | <u>Yes</u> |
| Leak Detection Monitoring Services:   | <u>Yes</u> | Other:  |            | UST Piping/Sump Installation:   | <u>Yes</u> |
| Line Tightness Testing:   | <u>Yes</u> |   |            | UST System Removal:   | <u>Yes</u> |
| <b>Environmental Service Firms</b>  |            |   |            | Other:  |            |
| Emergency Cleanup - Spill/Release:  | No         | UST Compliance Consultants:   | <u>Yes</u> |   |            |
| Environmental Engineer/Geologist - Site Checks:                                   | No         | UST Equipment Verification:   | No         |   |            |
| Environmental Engineer/Geologist Soil and GW Cleanu                               | No         | Waste Disposal and Treatment:   | No         |   |            |
| Oil and Solvent Recycling:  | No         | Other:  |            |   |            |
| Soil and Water Testing Lab:   | No         |   |            |   |            |

| Company  |            | Listing Submitted  | 1/4/2022   | Area of state conducts work   |            |
|--|------------|--|------------|---|------------|
| <b>EnviroTrac Ltd.</b><br>7343 West Friendly Avenue<br>Suite J<br>Greensboro, NC 27410 |            | <b>Phone</b> (336) 763-6025<br><b>Fax</b><br><b>Website</b> <a href="http://envirotrac.com">envirotrac.com</a> |            | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |            |
| Compliance Testing and Monitoring  |            |  |            | UST Equipment Service Contractors   |            |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:   | No         | Dispenser Meter Repair/Calibration:   | No         |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:   | No         | Leak Detection Equipment Installation Servicing:  | No         |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:  | No         | Spill Bucket Installation Repair:   | No         |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:  | No         | UST Equipment Installation - Other:   | No         |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments):  | No         | UST Equipment Repair:   | No         |
| Leak Detection Equipment Operability Check:  | No         | UST Internal Lining Inspections:   | No         | UST System Installation - Complete Systems:   | No         |
| Leak Detection Monitoring Services:  | No         | Other:   |            | UST Piping/Sump Installation:   | No         |
| Line Tightness Testing:  | No         |  |            | UST System Removal:   | <u>Yes</u> |
| <b>Environmental Service Firms</b>   |            |  |            | Other:  |            |
| Emergency Cleanup - Spill/Release:   | <u>Yes</u> | UST Compliance Consultants:  | <u>Yes</u> |   |            |
| Environmental Engineer/Geologist - Site Checks:  | <u>Yes</u> | UST Equipment Verification:  | No         |   |            |
| Environmental Engineer/Geologist Soil and GW Cleanu                                    | <u>Yes</u> | Waste Disposal and Treatment:  | No         |   |            |
| Oil and Solvent Recycling:   | No         | Other:   |            |   |            |
| Soil and Water Testing Lab:  | <u>Yes</u> |  |            |   |            |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     | Listing Submitted  |    | 7/30/2020  |  | Area of state conducts work   |    |
|---|-----|--|----|--|--|---|----|
| Envirovation Geologic Consulting and Mapping, PC<br>719-A Greenway Rd<br>PO Box 3425<br>Boone, NC 28607 |     | Phone (828) 407-0613<br><br>Fax<br><br>Website <a href="https://envirovationconsulting.com/">https://envirovationconsulting.com/</a> |    |  |  | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |    |
| Compliance Testing and Monitoring   |     |  |    | UST Equipment Service Contractors                |  |   |    |
| Automatic Line Leak Detector Testing:   | No  | Overfill Prevention Equipment Operability Check:   | No | Dispenser Meter Repair/Calibration:              |  |   | No |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:   | No | Leak Detection Equipment Installation Servicing: |  |   | No |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:  | No | Spill Bucket Installation Repair:                |  |   | No |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:  | No | UST Equipment Installation - Other:              |  |   | No |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments):  | No | UST Equipment Repair:                            |  |   | No |
| Leak Detection Equipment Operability Check:   | No  | UST Internal Lining Inspections:   | No | UST System Installation - Complete Systems:      |  |   | No |
| Leak Detection Monitoring Services:   | No  | Other:   |    | UST Piping/Sump Installation:                    |  |   | No |
| Line Tightness Testing:   | No  |  |    | UST System Removal:                              |  |   | No |
| Environmental Service Firms   |     |  |    | Other:   |  |   |    |
| Emergency Cleanup - Spill/Release:  | Yes | UST Compliance Consultants:  | No |  |  |   |    |
| Environmental Engineer/Geologist - Site Checks:   | Yes | UST Equipment Verification:  | No |  |  |   |    |
| Environmental Engineer/Geologist Soil and GW Cleanu   | Yes | Waste Disposal and Treatment:  | No |  |  |   |    |
| Oil and Solvent Recycling:  | No  | Other:   |    |  |  |   |    |
| Soil and Water Testing Lab:   | No  |  |    |  |  |   |    |

| Company  |     | Listing Submitted   |                         | 1/3/2022   |  | Area of state conducts work  |     |
|--|-----|---|-------------------------|--|--|--|-----|
| Evo Corporation<br>1703 Vargrave Street<br>Winston-Salem, NC 27107 |     | Phone (336) 725-5844<br><br>Fax<br><br>Website <a href="http://www.evocorp.net">www.evocorp.net</a> |                         |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |     |
| Compliance Testing and Monitoring                                  |     |   |                         | UST Equipment Service Contractors                |  |  |     |
| Automatic Line Leak Detector Testing:                              | No  | Overfill Prevention Equipment Operability Check:  | No                      | Dispenser Meter Repair/Calibration:              |  |  | No  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:  | No                      | Leak Detection Equipment Installation Servicing: |  |  | No  |
| Corrosion Protection Design Experts:                               | No  | Spill Prevention Equipment Testing:   | No                      | Spill Bucket Installation Repair:                |  |  | No  |
| Corrosion Protection System Repairs:                               | No  | Tank Tightness Testing:   | No                      | UST Equipment Installation - Other:              |  |  | No  |
| Corrosion Protection System Testing:                               | No  | UST Internal Inspections (Integrity Assessments):   | No                      | UST Equipment Repair:                            |  |  | No  |
| Leak Detection Equipment Operability Check:                        | No  | UST Internal Lining Inspections:  | No                      | UST System Installation - Complete Systems:      |  |  | No  |
| Leak Detection Monitoring Services:                                | No  | Other:  |                         | UST Piping/Sump Installation:                    |  |  | No  |
| Line Tightness Testing:  | No  |   |                         | UST System Removal:                              |  |  | Yes |
| Environmental Service Firms  |     |   |                         | Other: Vacuum Truck Services                     |  |  |     |
| Emergency Cleanup - Spill/Release:                                 | Yes | UST Compliance Consultants:   | No                      |  |  |  |     |
| Environmental Engineer/Geologist - Site Checks:                    | No  | UST Equipment Verification:   | No                      |  |  |  |     |
| Environmental Engineer/Geologist Soil and GW Cleanu                | No  | Waste Disposal and Treatment:   | Yes                     |  |  |  |     |
| Oil and Solvent Recycling:   | Yes | Other:  | Transportation Services |  |  |  |     |
| Soil and Water Testing Lab:  | No  |   |                         |  |  |  |     |

| Company   |            | Listing Submitted  |                         | 1/3/2022   |   | Area of state conducts work |  |
|---|------------|--|-------------------------|--|---|-----------------------------|--|
| <b>Evo Corporation</b><br>1703 Vargrave Street<br>Winston-Salem, NC 27107 |            | <b>Phone</b> (336) 725-5844<br><b>Fax</b><br><b>Website</b> <a href="http://www.evocorp.net">www.evocorp.net</a> |                         |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |                             |  |
| Compliance Testing and Monitoring   |            |  |                         |  | UST Equipmment Service Contractors  |                             |  |
| Automatic Line Leak Detector Testing:                                     | No         | Overfill Prevention Equipment Operability Check:   | No                      | Dispenser Meter Repair/Calibration:              | No  |                             |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:   | No                      | Leak Detection Equipment Installation Servicing: | No  |                             |  |
| Corrosion Protection Design Experts:                                      | No         | Spill Prevention Equipment Testing:  | No                      | Spill Bucket Installation Repair:                | No  |                             |  |
| Corrosion Protection System Repairs:                                      | No         | Tank Tightness Testing:  | No                      | UST Equipment Installation - Other:              | No  |                             |  |
| Corrosion Protection System Testing:                                      | No         | UST Internal Inspections (Integrity Assessments):  | No                      | UST Equipment Repair:                            | No  |                             |  |
| Leak Detection Equipment Operability Check:                               | No         | UST Internal Lining Inspections:   | No                      | UST System Installation - Complete Systems:      | No  |                             |  |
| Leak Detection Monitoring Services:                                       | No         | Other:   |                         | UST Piping/Sump Installation:                    | No  |                             |  |
| Line Tightness Testing:   | No         |  |                         | UST System Removal:                              | <u>Yes</u>  |                             |  |
| Environmental Service Firms   |            |  |                         |  | Other:  | Vacuum Truck Services       |  |
| Emergency Cleanup - Spill/Release:  | <u>Yes</u> | UST Compliance Consultants:  | No                      |  |   |                             |  |
| Environmental Engineer/Geologist - Site Checks:                           | No         | UST Equipment Verification:  | No                      |  |   |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                       | No         | Waste Disposal and Treatment:  | <u>Yes</u>              |  |   |                             |  |
| Oil and Solvent Recycling:  | <u>Yes</u> | Other:   | Transportation Services |  |   |                             |  |
| Soil and Water Testing Lab:   | No         |  |                         |  |   |                             |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     |  |     | Listing Submitted                                | 7/29/2020 | Area of state conducts work  |  |
|--|-----|--|-----|--|-----------|--|--|
| Excel Environmental Associates, PLLC<br>625 Huntsman Court<br>Gastonia, NC 28054 |     | Phone (704) 853-0800<br>Fax (704) 853-3949<br>Website <a href="http://www.excelengr.com">www.excelengr.com</a> |     |  |           | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring  |     |  |     |  |           | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:   | No  | Dispenser Meter Repair/Calibration:              |           | No   |  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:   | No  | Leak Detection Equipment Installation Servicing: |           | No   |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:  | No  | Spill Bucket Installation Repair:                |           | No   |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:  | No  | UST Equipment Installation - Other:              |           | No   |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):  | No  | UST Equipment Repair:                            |           | No   |  |
| Leak Detection Equipment Operability Check:                                      | No  | UST Internal Lining Inspections:   | No  | UST System Installation - Complete Systems:      |           | No   |  |
| Leak Detection Monitoring Services:  | No  | Other:   |     | UST Piping/Sump Installation:                    |           | No   |  |
| Line Tightness Testing:  | No  |  |     | UST System Removal:                              |           | No   |  |
| Environmental Service Firms  |     |  |     |  |           | Other:   |  |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:  | Yes |  |           |  |  |
| Environmental Engineer/Geologist - Site Checks:                                  | Yes | UST Equipment Verification:  | No  |  |           |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                              | Yes | Waste Disposal and Treatment:  | No  |  |           |  |  |
| Oil and Solvent Recycling:   | No  | Other:   |     |  |           |  |  |
| Soil and Water Testing Lab:  | No  |  |     |  |           |  |  |

| Company   |     |  |                       | Listing Submitted                                | 1/1/2022 | Area of state conducts work  |  |
|---|-----|--|-----------------------|--|----------|--|--|
| Galloway<br>6162 South Willow Drive<br>Suite 320<br>Greenwood Village, CO 80111 |     | Phone (303) 770-8884<br>Fax (303) 770-3636<br>Website <a href="http://www.Gallowayus.com">www.Gallowayus.com</a> |                       |  |          | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring   |     |  |                       |  |          | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:   | No  | Overfill Prevention Equipment Operability Check:   | No                    | Dispenser Meter Repair/Calibration:              |          | No   |  |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:   | No                    | Leak Detection Equipment Installation Servicing: |          | No   |  |
| Corrosion Protection Design Experts:  | Yes | Spill Prevention Equipment Testing:  | No                    | Spill Bucket Installation Repair:                |          | No   |  |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:  | No                    | UST Equipment Installation - Other:              |          | No   |  |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments):  | No                    | UST Equipment Repair:                            |          | No   |  |
| Leak Detection Equipment Operability Check:                                     | No  | UST Internal Lining Inspections:   | No                    | UST System Installation - Complete Systems:      |          | No   |  |
| Leak Detection Monitoring Services:   | No  | Other:   | UST/AST System Design | UST Piping/Sump Installation:                    |          | No   |  |
| Line Tightness Testing:   | No  |  |                       | UST System Removal:                              |          | No   |  |
| Environmental Service Firms   |     |  |                       |  |          | Other:   |  |
| Emergency Cleanup - Spill/Release:  | No  | UST Compliance Consultants:  | Yes                   |  |          |  |  |
| Environmental Engineer/Geologist - Site Checks:                                 | No  | UST Equipment Verification:  | No                    |  |          |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                             | No  | Waste Disposal and Treatment:  | No                    |  |          |  |  |
| Oil and Solvent Recycling:  | No  | Other:   | UST/AST System Design |  |          |  |  |
| Soil and Water Testing Lab:   | No  |  |                       |  |          |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |            | Listing Submitted   |    | 12/30/2021                                       |  | Area of state conducts work  |            |
|---|------------|---|----|--|--|--|------------|
| Geo-Hydro Engineers, Inc.<br>2748 Interstate Street<br>Suite A<br>Charlotte, NC 28208 |            | Phone (704) 837-7174<br><br>Fax<br><br>Website <a href="http://www.geohydro.com">www.geohydro.com</a> |    |  |  | Coastal (East of I-95): Yes<br><br>Central (West of I-95 and East of I-77): Yes<br><br>Mountains (West of I-77): Yes |            |
| Compliance Testing and Monitoring   |            |   |    | UST Equipment Service Contractors                |  |  |            |
| Automatic Line Leak Detector Testing:   | No         | Overfill Prevention Equipment Operability Check:  | No | Dispenser Meter Repair/Calibration:              |  |  | No         |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:  | No | Leak Detection Equipment Installation Servicing: |  |  | No         |
| Corrosion Protection Design Experts:  | No         | Spill Prevention Equipment Testing:   | No | Spill Bucket Installation Repair:                |  |  | No         |
| Corrosion Protection System Repairs:  | No         | Tank Tightness Testing:   | No | UST Equipment Installation - Other:              |  |  | No         |
| Corrosion Protection System Testing:  | No         | UST Internal Inspections (Integrity Assessments):   | No | UST Equipment Repair:                            |  |  | No         |
| Leak Detection Equipment Operability Check:   | No         | UST Internal Lining Inspections:  | No | UST System Installation - Complete Systems:      |  |  | No         |
| Leak Detection Monitoring Services:   | No         | Other:  |    | UST Piping/Sump Installation:                    |  |  | No         |
| Line Tightness Testing:   | No         |   |    | UST System Removal:                              |  |  | <u>Yes</u> |
| Environmental Service Firms   |            |   |    | Other:   |  |  |            |
| Emergency Cleanup - Spill/Release:  | No         | UST Compliance Consultants:   | No |  |  |  |            |
| Environmental Engineer/Geologist - Site Checks:                                       | <u>Yes</u> | UST Equipment Verification:   | No |  |  |  |            |
| Environmental Engineer/Geologist Soil and GW Cleanu                                   | <u>Yes</u> | Waste Disposal and Treatment:   | No |  |  |  |            |
| Oil and Solvent Recycling:  | No         | Other:  |    |  |  |  |            |
| Soil and Water Testing Lab:   | No         |   |    |  |  |  |            |

| Company   |            | Listing Submitted  |    | 1/3/2022   |  | Area of state conducts work  |            |
|---|------------|--|----|--|--|--|------------|
| Geological Resources, Inc.<br>3502 Hayes Road<br>Monroe, NC 28112 |            | Phone (704) 845-4010<br><br>Fax (704) 845-4012<br><br>Website <a href="http://grienv.com">grienv.com</a> |    |  |  | Coastal (East of I-95): Yes<br><br>Central (West of I-95 and East of I-77): Yes<br><br>Mountains (West of I-77): Yes |            |
| Compliance Testing and Monitoring                                 |            |  |    | UST Equipment Service Contractors                |  |  |            |
| Automatic Line Leak Detector Testing:                             | No         | Overfill Prevention Equipment Operability Check:   | No | Dispenser Meter Repair/Calibration:              |  |  | No         |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:   | No | Leak Detection Equipment Installation Servicing: |  |  | No         |
| Corrosion Protection Design Experts:                              | No         | Spill Prevention Equipment Testing:  | No | Spill Bucket Installation Repair:                |  |  | No         |
| Corrosion Protection System Repairs:                              | No         | Tank Tightness Testing:  | No | UST Equipment Installation - Other:              |  |  | No         |
| Corrosion Protection System Testing:                              | No         | UST Internal Inspections (Integrity Assessments):  | No | UST Equipment Repair:                            |  |  | No         |
| Leak Detection Equipment Operability Check:                       | No         | UST Internal Lining Inspections:   | No | UST System Installation - Complete Systems:      |  |  | No         |
| Leak Detection Monitoring Services:                               | No         | Other:   |    | UST Piping/Sump Installation:                    |  |  | No         |
| Line Tightness Testing:   | No         |  |    | UST System Removal:                              |  |  | <u>Yes</u> |
| Environmental Service Firms                                       |            |  |    | Other:   |  |  |            |
| Emergency Cleanup - Spill/Release:                                | <u>Yes</u> | UST Compliance Consultants:  | No |  |  |  |            |
| Environmental Engineer/Geologist - Site Checks:                   | <u>Yes</u> | UST Equipment Verification:  | No |  |  |  |            |
| Environmental Engineer/Geologist Soil and GW Cleanu               | <u>Yes</u> | Waste Disposal and Treatment:  | No |  |  |  |            |
| Oil and Solvent Recycling:  | No         | Other:   |    |  |  |  |            |
| Soil and Water Testing Lab:                                       | No         |  |    |  |  |  |            |

| Company  |            | Listing Submitted   |    | 1/3/2022   |   | Area of state conducts work |  |
|--|------------|---|----|--|---|-----------------------------|--|
| <b>Geological Resources, Inc.</b><br>3502 Hayes Road<br>Monroe, NC 28112 |            | <b>Phone</b> (704) 845-4010<br><b>Fax</b> (704) 845-4012<br><b>Website</b> <a href="http://grienv.com">grienv.com</a> |    |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |                             |  |
| Compliance Testing and Monitoring  |            |   |    |  | UST Equipment Service Contractors   |                             |  |
| Automatic Line Leak Detector Testing:                                    | No         | Overfill Prevention Equipment Operability Check:  | No | Dispenser Meter Repair/Calibration:              | No  |                             |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:  | No | Leak Detection Equipment Installation Servicing: | No  |                             |  |
| Corrosion Protection Design Experts:                                     | No         | Spill Prevention Equipment Testing:   | No | Spill Bucket Installation Repair:                | No  |                             |  |
| Corrosion Protection System Repairs:                                     | No         | Tank Tightness Testing:   | No | UST Equipment Installation - Other:              | No  |                             |  |
| Corrosion Protection System Testing:                                     | No         | UST Internal Inspections (Integrity Assessments):   | No | UST Equipment Repair:                            | No  |                             |  |
| Leak Detection Equipment Operability Check:                              | No         | UST Internal Lining Inspections:  | No | UST System Installation - Complete Systems:      | No  |                             |  |
| Leak Detection Monitoring Services:                                      | No         | Other:  |    | UST Piping/Sump Installation:                    | No  |                             |  |
| Line Tightness Testing:  | No         |   |    | UST System Removal:                              | <u>Yes</u>  |                             |  |
| Environmental Service Firms  |            |   |    |  | Other:  |                             |  |
| Emergency Cleanup - Spill/Release:                                       | <u>Yes</u> | UST Compliance Consultants:   | No |  |   |                             |  |
| Environmental Engineer/Geologist - Site Checks:                          | <u>Yes</u> | UST Equipment Verification:   | No |  |   |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                      | <u>Yes</u> | Waste Disposal and Treatment:   | No |  |   |                             |  |
| Oil and Solvent Recycling:   | No         | Other:  |    |  |   |                             |  |
| Soil and Water Testing Lab:  | No         |   |    |  |   |                             |  |



## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     |   |    | Listing Submitted                                | 11/18/2020 | Area of state conducts work  |  |
|---|-----|---|----|--|------------|--|--|
| Groundwater Management Associates, Inc.<br>4300 Sapphire Court<br>Suite 100<br>Greenville, NC 27834 |     | Phone (252) 758-3310<br><br>Fax<br><br>Website <a href="http://www.gma-nc.com">www.gma-nc.com</a> |    |  |            | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring   |     |   |    |  |            | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:   | No  | Overfill Prevention Equipment Operability Check:  | No | Dispenser Meter Repair/Calibration:              |            | No   |  |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:  | No | Leak Detection Equipment Installation Servicing: |            | No   |  |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:   | No | Spill Bucket Installation Repair:                |            | No   |  |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:   | No | UST Equipment Installation - Other:              |            | No   |  |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments):   | No | UST Equipment Repair:                            |            | No   |  |
| Leak Detection Equipment Operability Check:   | No  | UST Internal Lining Inspections:  | No | UST System Installation - Complete Systems:      |            | No   |  |
| Leak Detection Monitoring Services:   | No  | Other:  |    | UST Piping/Sump Installation:                    |            | No   |  |
| Line Tightness Testing:   | No  |   |    | UST System Removal:                              |            | No   |  |
| Environmental Service Firms   |     |   |    |  |            | Other:   |  |
| Emergency Cleanup - Spill/Release:  | No  | UST Compliance Consultants:   | No |  |            |  |  |
| Environmental Engineer/Geologist - Site Checks:   | Yes | UST Equipment Verification:   | No |  |            |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | Yes | Waste Disposal and Treatment:   | No |  |            |  |  |
| Oil and Solvent Recycling:  | No  | Other:  |    |  |            |  |  |
| Soil and Water Testing Lab:   | No  |   |    |  |            |  |  |

| Company   |     |   |     | Listing Submitted                                | 12/30/2021 | Area of state conducts work  |  |
|---|-----|---|-----|--|------------|--|--|
| Highlands Environmental Solutions, Inc.<br>8410-d Falls of Neuse<br>Raleigh, NC 27615 |     | Phone (919) 848-3155<br><br>Fax<br><br>Website <a href="http://www.HESfast.com">www.HESfast.com</a> |     |  |            | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring   |     |   |     |  |            | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:   | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              |            | No   |  |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:  | No  | Leak Detection Equipment Installation Servicing: |            | No   |  |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:   | No  | Spill Bucket Installation Repair:                |            | No   |  |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:   | No  | UST Equipment Installation - Other:              |            | No   |  |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments):   | No  | UST Equipment Repair:                            |            | No   |  |
| Leak Detection Equipment Operability Check:   | No  | UST Internal Lining Inspections:  | No  | UST System Installation - Complete Systems:      |            | No   |  |
| Leak Detection Monitoring Services:   | No  | Other:  |     | UST Piping/Sump Installation:                    |            | No   |  |
| Line Tightness Testing:   | No  |   |     | UST System Removal:                              |            | No   |  |
| Environmental Service Firms   |     |   |     |  |            | Other:   |  |
| Emergency Cleanup - Spill/Release:  | Yes | UST Compliance Consultants:   | Yes |  |            |  |  |
| Environmental Engineer/Geologist - Site Checks:                                       | Yes | UST Equipment Verification:   | No  |  |            |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                                   | Yes | Waste Disposal and Treatment:   | No  |  |            |  |  |
| Oil and Solvent Recycling:  | No  | Other:  |     |  |            |  |  |
| Soil and Water Testing Lab:   | No  |   |     |  |            |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     |   |     | Listing Submitted                                | 1/14/2020 | Area of state conducts work   |  |
|--|-----|---|-----|--|-----------|---|--|
| INENCO, INC.<br>132 W STATESVILLE AVE<br>MOORESVILLE, NC 28115 |     | Phone (704) 662-8192<br>Fax (704) 662-8194<br>Website |     |  |           | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring                              |     |   |     |  |           | UST Equipment Service Contractors   |  |
| Automatic Line Leak Detector Testing:                          | No  | Overfill Prevention Equipment Operability Check:      | No  | Dispenser Meter Repair/Calibration:              |           | No  |  |
| Containment Sump Testing:                                      | No  | Statistical Inventory Reconciliation Services:        | No  | Leak Detection Equipment Installation Servicing: |           | No  |  |
| Corrosion Protection Design Experts:                           | No  | Spill Prevention Equipment Testing:                   | No  | Spill Bucket Installation Repair:                |           | No  |  |
| Corrosion Protection System Repairs:                           | No  | Tank Tightness Testing:                               | No  | UST Equipment Installation - Other:              |           | No  |  |
| Corrosion Protection System Testing:                           | No  | UST Internal Inspections (Integrity Assessments):     | No  | UST Equipment Repair:                            |           | No  |  |
| Leak Detection Equipment Operability Check:                    | No  | UST Internal Lining Inspections:                      | No  | UST System Installation - Complete Systems:      |           | No  |  |
| Leak Detection Monitoring Services:                            | No  | Other:  |     | UST Piping/Sump Installation:                    |           | No  |  |
| Line Tightness Testing:  | No  |   |     | UST System Removal:                              |           | No  |  |
| Environmental Service Firms                                    |     |   |     |  |           | Other:  |  |
| Emergency Cleanup - Spill/Release:                             | No  | UST Compliance Consultants:                           | Yes |  |           |   |  |
| Environmental Engineer/Geologist - Site Checks:                | Yes | UST Equipment Verification:                           | No  |  |           |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu            | Yes | Waste Disposal and Treatment:                         | No  |  |           |   |  |
| Oil and Solvent Recycling:                                     | No  | Other:  |     |  |           |   |  |
| Soil and Water Testing Lab:                                    | No  |   |     |  |           |   |  |

| Company  |     |   |                              | Listing Submitted                                | 1/5/2022 | Area of state conducts work  |  |
|--|-----|---|------------------------------|--|----------|--|--|
| Johnson, Spellman & Associates, Inc.<br>350 Research Ct.<br>Suite 130<br>Peachtree Corners, GA 30092 |     | Phone (770) 447-4555<br>Fax<br>Website            |                              |  |          | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring  |     |   |                              |  |          | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:  | Yes                          | Dispenser Meter Repair/Calibration:              |          | No   |  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:    | No                           | Leak Detection Equipment Installation Servicing: |          | No   |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:               | No                           | Spill Bucket Installation Repair:                |          | No   |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:                           | No                           | UST Equipment Installation - Other:              |          | No   |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments): | No                           | UST Equipment Repair:                            |          | No   |  |
| Leak Detection Equipment Operability Check:  | Yes | UST Internal Lining Inspections:                  | No                           | UST System Installation - Complete Systems:      |          | No   |  |
| Leak Detection Monitoring Services:  | No  | Other:  | Engineering- Design Services | UST Piping/Sump Installation:                    |          | No   |  |
| Line Tightness Testing:  | No  |   |                              | UST System Removal:                              |          | No   |  |
| Environmental Service Firms  |     |   |                              |  |          | Other:   |  |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                       | Yes                          |  |          |  |  |
| Environmental Engineer/Geologist - Site Checks:  | No  | UST Equipment Verification:                       | Yes                          |  |          |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No  | Waste Disposal and Treatment:                     | No                           |  |          |  |  |
| Oil and Solvent Recycling:   | No  | Other:  | Engineering-Design Services  |  |          |  |  |
| Soil and Water Testing Lab:  | No  |   |                              |  |          |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |            | Listing Submitted                                 |                     | 5/27/2020  |  | Area of state conducts work  |  |
|--|------------|---|---------------------|--|--|--|--|
| Labrador Environmental Consultants, P.C. (eastern<br>1450 Johnson Drive<br>Williamston, NC 27892 |            | Phone (252) 809-9130<br><br>Fax<br><br>Website    |                     |  |  | Coastal (East of I-95): Yes<br><br>Central (West of I-95 and East of I-77): Yes<br><br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring  |            |   |                     | UST Equipment Service Contractors                |  |  |  |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:  | No                  | Dispenser Meter Repair/Calibration:              |  | No   |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:    | No                  | Leak Detection Equipment Installation Servicing: |  | No   |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:               | No                  | Spill Bucket Installation Repair:                |  | No   |  |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:                           | No                  | UST Equipment Installation - Other:              |  | No   |  |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments): | No                  | UST Equipment Repair:                            |  | No   |  |
| Leak Detection Equipment Operability Check:  | No         | UST Internal Lining Inspections:                  | No                  | UST System Installation - Complete Systems:      |  | No   |  |
| Leak Detection Monitoring Services:  | No         | Other:  |                     | UST Piping/Sump Installation:                    |  | No   |  |
| Line Tightness Testing:  | No         |   |                     | UST System Removal:                              |  | No   |  |
| Environmental Service Firms  |            |   |                     | Other:   |  |  |  |
| Emergency Cleanup - Spill/Release:   | <u>Yes</u> | UST Compliance Consultants:                       | No                  |  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:  | <u>Yes</u> | UST Equipment Verification:                       | No                  |  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | <u>Yes</u> | Waste Disposal and Treatment:                     | <u>Yes</u>          |  |  |  |  |
| Oil and Solvent Recycling:   | No         | Other:  | UST removal/closure |  |  |  |  |
| Soil and Water Testing Lab:  | No         |   |                     |  |  |  |  |

| Company   |   | Listing Submitted                                 | 8/18/2020 | Area of state conducts work  |     |
|---|---|---|-----------|--|-----|
| Law Petroleum, Inc.<br>11025 Arlington Church Road<br>Charlotte, NC 28227 | Phone (704) 573-3535<br>Fax (704) 573-3535<br>Website |   |           | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |     |
| Compliance Testing and Monitoring   |   |   |           | UST Equipmment Service Contractors   |     |
| Automatic Line Leak Detector Testing:                                     | Yes   | Overfill Prevention Equipment Operability Check:  | Yes       | Dispenser Meter Repair/Calibration:  | No  |
| Containment Sump Testing:   | Yes   | Statistical Inventory Reconciliation Services:    | No        | Leak Detection Equipment Installation Servicing:   | Yes |
| Corrosion Protection Design Experts:                                      | No  | Spill Prevention Equipment Testing:               | Yes       | Spill Bucket Installation Repair:  | Yes |
| Corrosion Protection System Repairs:                                      | Yes   | Tank Tightness Testing:                           | Yes       | UST Equipment Installation - Other:  | Yes |
| Corrosion Protection System Testing:                                      | Yes   | UST Internal Inspections (Integrity Assessments): | Yes       | UST Equipment Repair:  | Yes |
| Leak Detection Equipment Operability Check:                               | Yes   | UST Internal Lining Inspections:                  | Yes       | UST System Installation - Complete Systems:  | Yes |
| Leak Detection Monitoring Services:                                       | Yes   | Other:  |           | UST Piping/Sump Installation:  | Yes |
| Line Tightness Testing:   | Yes   |   |           | UST System Removal:  | Yes |
| Environmental Service Firms   |   |   |           | Other:   |     |
| Emergency Cleanup - Spill/Release:  | Yes   | UST Compliance Consultants:                       | Yes       |  |     |
| Environmental Engineer/Geologist - Site Checks:                           | No  | UST Equipment Verification:                       | Yes       |  |     |
| Environmental Engineer/Geologist Soil and GW Cleanu                       | No  | Waste Disposal and Treatment:                     | No        |  |     |
| Oil and Solvent Recycling:  | No  | Other:  |           |  |     |
| Soil and Water Testing Lab:   | No  |   |           |  |     |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     |   | Listing Submitted  | 8/10/2021  | Area of state conducts work   |  |
|---|-----|---|--|--|---|--|
| Martin & Slagle GeoSciences, PA<br>173 Sloan Road<br>Franklin, NC 28734 |     |   | Phone 8286347741<br><br>Fax<br><br>Website martinandslagle.com |  | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring                                       |     |   |  | UST Equipment Service Contractors                |   |  |
| Automatic Line Leak Detector Testing:                                   | No  | Overfill Prevention Equipment Operability Check:  | No   | Dispenser Meter Repair/Calibration:              | No  |  |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:    | No   | Leak Detection Equipment Installation Servicing: | No  |  |
| Corrosion Protection Design Experts:                                    | No  | Spill Prevention Equipment Testing:               | No   | Spill Bucket Installation Repair:                | No  |  |
| Corrosion Protection System Repairs:                                    | No  | Tank Tightness Testing:                           | No   | UST Equipment Installation - Other:              | No  |  |
| Corrosion Protection System Testing:                                    | No  | UST Internal Inspections (Integrity Assessments): | No   | UST Equipment Repair:                            | No  |  |
| Leak Detection Equipment Operability Check:                             | No  | UST Internal Lining Inspections:                  | No   | UST System Installation - Complete Systems:      | No  |  |
| Leak Detection Monitoring Services:                                     | No  | Other:  |  | UST Piping/Sump Installation:                    | No  |  |
| Line Tightness Testing:   | No  |   |  | UST System Removal:                              | No  |  |
| Environmental Service Firms   |     |   |  | Other:   |   |  |
| Emergency Cleanup - Spill/Release:                                      | No  | UST Compliance Consultants:                       | No   |  |   |  |
| Environmental Engineer/Geologist - Site Checks:                         | Yes | UST Equipment Verification:                       | No   |  |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                     | Yes | Waste Disposal and Treatment:                     | Yes  |  |   |  |
| Oil and Solvent Recycling:  | No  | Other:  |  |  |   |  |
| Soil and Water Testing Lab:   | No  |   |  |  |   |  |

| Company   |     |   | Listing Submitted   | 1/31/2022  | Area of state conducts work  |  |
|---|-----|---|---|--|--|--|
| McCallum, P.C.<br>1808 Hayward Avenue<br>Chesapeake, VA 23320 |     |   | Phone (757) 420-9252<br><br>Fax (757) 424-2874<br><br>Website www.mccallumtestinglabs.com |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): No<br>Mountains (West of I-77): No |  |
| Compliance Testing and Monitoring                             |     |   |   | UST Equipment Service Contractors                |  |  |
| Automatic Line Leak Detector Testing:                         | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              | No   |  |
| Containment Sump Testing:                                     | No  | Statistical Inventory Reconciliation Services:    | No  | Leak Detection Equipment Installation Servicing: | No   |  |
| Corrosion Protection Design Experts:                          | No  | Spill Prevention Equipment Testing:               | No  | Spill Bucket Installation Repair:                | No   |  |
| Corrosion Protection System Repairs:                          | No  | Tank Tightness Testing:                           | No  | UST Equipment Installation - Other:              | No   |  |
| Corrosion Protection System Testing:                          | No  | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair:                            | No   |  |
| Leak Detection Equipment Operability Check:                   | No  | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems:      | No   |  |
| Leak Detection Monitoring Services:                           | No  | Other:  |   | UST Piping/Sump Installation:                    | No   |  |
| Line Tightness Testing:                                       | No  |   |   | UST System Removal:                              | No   |  |
| Environmental Service Firms                                   |     |   |   | Other:   |  |  |
| Emergency Cleanup - Spill/Release:                            | No  | UST Compliance Consultants:                       | No  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:               | Yes | UST Equipment Verification:                       | No  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu           | Yes | Waste Disposal and Treatment:                     | No  |  |  |  |
| Oil and Solvent Recycling:                                    | No  | Other:  |   |  |  |  |
| Soil and Water Testing Lab:                                   | No  |   |   |  |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |            |   |            | Listing Submitted                                | 1/3/2020 | Area of state conducts work  |  |
|---|------------|---|------------|--|----------|--|--|
| <b>MGF Environmental, PLLC</b><br>288 Gap Creek Rd.<br>Fletcher, NC 28732 |            | <b>Phone</b> (904) 814-3680<br><b>Fax</b><br><b>Website</b> <a href="http://www.mgfenvironmental.com">http://www.mgfenvironmental.com</a> |            |  |          | <b>Coastal (East of I-95):</b> No<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring   |            |   |            |  |          | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:                                     | No         | Overfill Prevention Equipment Operability Check:  | No         | Dispenser Meter Repair/Calibration:              |          | No   |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:  | No         | Leak Detection Equipment Installation Servicing: |          | No   |  |
| Corrosion Protection Design Experts:                                      | No         | Spill Prevention Equipment Testing:   | No         | Spill Bucket Installation Repair:                |          | No   |  |
| Corrosion Protection System Repairs:                                      | No         | Tank Tightness Testing:   | No         | UST Equipment Installation - Other:              |          | No   |  |
| Corrosion Protection System Testing:                                      | No         | UST Internal Inspections (Integrity Assessments):   | No         | UST Equipment Repair:                            |          | No   |  |
| Leak Detection Equipment Operability Check:                               | No         | UST Internal Lining Inspections:  | No         | UST System Installation - Complete Systems:      |          | No   |  |
| Leak Detection Monitoring Services:                                       | No         | Other:  |            | UST Piping/Sump Installation:                    |          | No   |  |
| Line Tightness Testing:   | No         |   |            | UST System Removal:                              |          | <u>Yes</u>   |  |
| Environmental Service Firms   |            |   |            |  |          | Other:   |  |
| Emergency Cleanup - Spill/Release:  | <u>Yes</u> | UST Compliance Consultants:   | <u>Yes</u> |  |          |  |  |
| Environmental Engineer/Geologist - Site Checks:                           | <u>Yes</u> | UST Equipment Verification:   | No         |  |          |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                       | <u>Yes</u> | Waste Disposal and Treatment:   | <u>Yes</u> |  |          |  |  |
| Oil and Solvent Recycling:  | No         | Other:  |            |  |          |  |  |
| Soil and Water Testing Lab:   | No         |   |            |  |          |  |  |

| Company   |            |   |            | Listing Submitted                                | 9/8/2022 | Area of state conducts work   |  |
|---|------------|---|------------|--|----------|---|--|
| <b>Mid-Atlantic Associates, Inc.</b><br>409 Rogers View Ct<br>Raleigh, NC 27610 |            | <b>Phone</b> (919) 250-9918<br><b>Fax</b> (919) 250-9950<br><b>Website</b> <a href="http://www.maaonline.com">www.maaonline.com</a> |            |  |          | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring   |            |   |            |  |          | UST Equipment Service Contractors   |  |
| Automatic Line Leak Detector Testing:   | No         | Overfill Prevention Equipment Operability Check:  | No         | Dispenser Meter Repair/Calibration:              |          | No  |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:  | No         | Leak Detection Equipment Installation Servicing: |          | No  |  |
| Corrosion Protection Design Experts:  | No         | Spill Prevention Equipment Testing:   | No         | Spill Bucket Installation Repair:                |          | No  |  |
| Corrosion Protection System Repairs:  | No         | Tank Tightness Testing:   | No         | UST Equipment Installation - Other:              |          | No  |  |
| Corrosion Protection System Testing:  | No         | UST Internal Inspections (Integrity Assessments):   | No         | UST Equipment Repair:                            |          | No  |  |
| Leak Detection Equipment Operability Check:                                     | No         | UST Internal Lining Inspections:  | No         | UST System Installation - Complete Systems:      |          | No  |  |
| Leak Detection Monitoring Services:   | No         | Other:  |            | UST Piping/Sump Installation:                    |          | No  |  |
| Line Tightness Testing:   | No         |   |            | UST System Removal:                              |          | No  |  |
| Environmental Service Firms   |            |   |            |  |          | Other:  |  |
| Emergency Cleanup - Spill/Release:  | <u>Yes</u> | UST Compliance Consultants:   | No         |  |          |   |  |
| Environmental Engineer/Geologist - Site Checks:                                 | <u>Yes</u> | UST Equipment Verification:   | No         |  |          |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                             | <u>Yes</u> | Waste Disposal and Treatment:   | <u>Yes</u> |  |          |   |  |
| Oil and Solvent Recycling:  | No         | Other:  |            |  |          |   |  |
| Soil and Water Testing Lab:   | No         |   |            |  |          |   |  |

| Company  |            | Listing Submitted                                 |  | 9/8/2022   |  | Area of state conducts work                  |  |
|--|------------|---|--|--|--|--|--|
| Mid-Atlantic Associates, Inc.<br>409 Rogers View Ct<br>Raleigh, NC 27610 |            | Phone   | (919) 250-9918   |  |  | Coastal (East of I-95): Yes                  |  |
|  |            | Fax   | (919) 250-9950   |  |  | Central (West of I-95 and East of I-77): Yes |  |
|  |            | Website   | <a href="http://www.maaonline.com">www.maaonline.com</a> |  |  | Mountains (West of I-77): Yes                |  |
| Compliance Testing and Monitoring  |            |   |  | UST Equipment Service Contractors                |  |  |  |
| Automatic Line Leak Detector Testing:                                    | No         | Overfill Prevention Equipment Operability Check:  | No   | Dispenser Meter Repair/Calibration:              |  | No   |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:    | No   | Leak Detection Equipment Installation Servicing: |  | No   |  |
| Corrosion Protection Design Experts:                                     | No         | Spill Prevention Equipment Testing:               | No   | Spill Bucket Installation Repair:                |  | No   |  |
| Corrosion Protection System Repairs:                                     | No         | Tank Tightness Testing:                           | No   | UST Equipment Installation - Other:              |  | No   |  |
| Corrosion Protection System Testing:                                     | No         | UST Internal Inspections (Integrity Assessments): | No   | UST Equipment Repair:                            |  | No   |  |
| Leak Detection Equipment Operability Check:                              | No         | UST Internal Lining Inspections:                  | No   | UST System Installation - Complete Systems:      |  | No   |  |
| Leak Detection Monitoring Services:                                      | No         | Other:  |  | UST Piping/Sump Installation:                    |  | No   |  |
| Line Tightness Testing:  | No         |   |  | UST System Removal:                              |  | No   |  |
| Environmental Service Firms  |            |   |  | Other:   |  |  |  |
| Emergency Cleanup - Spill/Release:                                       | <u>Yes</u> | UST Compliance Consultants:                       | No   |  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:                          | <u>Yes</u> | UST Equipment Verification:                       | No   |  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                      | <u>Yes</u> | Waste Disposal and Treatment:                     | <u>Yes</u>   |  |  |  |  |
| Oil and Solvent Recycling:   | No         | Other:  |  |  |  |  |  |
| Soil and Water Testing Lab:  | No         |   |  |  |  |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |  |    |   | Listing Submitted   |                                  | 12/30/2021  |  | Area of state conducts work |  |
|---|--|----|---|---|----------------------------------|---|--|-----------------------------|--|
| <b>NCPCM</b><br>7300 glenwood ave.<br>raleigh, NC 27612 |  |    |   | <b>Phone</b> (919) 782-4411<br><b>Fax</b> (919) 782-4414<br><b>Website</b> <a href="http://www.ncpcm.org">www.ncpcm.org</a> |                                  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |                             |  |
| Compliance Testing and Monitoring                       |  |    |   |   |                                  | UST Equipment Service Contractors   |  |                             |  |
| Automatic Line Leak Detector Testing:                   |  | No | Overfill Prevention Equipment Operability Check:  |   | No                               | Dispenser Meter Repair/Calibration:   |  | No                          |  |
| Containment Sump Testing:                               |  | No | Statistical Inventory Reconciliation Services:    |   | No                               | Leak Detection Equipment Installation Servicing:  |  | No                          |  |
| Corrosion Protection Design Experts:                    |  | No | Spill Prevention Equipment Testing:               |   | No                               | Spill Bucket Installation Repair:   |  | No                          |  |
| Corrosion Protection System Repairs:                    |  | No | Tank Tightness Testing:                           |   | No                               | UST Equipment Installation - Other:   |  | No                          |  |
| Corrosion Protection System Testing:                    |  | No | UST Internal Inspections (Integrity Assessments): |   | No                               | UST Equipment Repair:   |  | No                          |  |
| Leak Detection Equipment Operability Check:             |  | No | UST Internal Lining Inspections:                  |   | No                               | UST System Installation - Complete Systems:   |  | No                          |  |
| Leak Detection Monitoring Services:                     |  | No | Other:  |   |                                  | UST Piping/Sump Installation:   |  | No                          |  |
| Line Tightness Testing:                                 |  | No |   |   |                                  | UST System Removal:   |  | No                          |  |
| Environmental Service Firms                             |  |    |   |   |                                  | Other:  |  |                             |  |
| Emergency Cleanup - Spill/Release:                      |  | No | UST Compliance Consultants:                       |   | <u>Yes</u>                       |   |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:         |  | No | UST Equipment Verification:                       |   | No                               |   |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu     |  | No | Waste Disposal and Treatment:                     |   | No                               |   |  |                             |  |
| Oil and Solvent Recycling:                              |  | No | Other:  |   | Engineering on UST Installations |   |  |                             |  |
| Soil and Water Testing Lab:                             |  | No |   |   |                                  |   |  |                             |  |

| Company   |  |            |   | Listing Submitted   |                                      | 7/30/2020   |  | Area of state conducts work |  |
|---|--|------------|---|---|--------------------------------------|---|--|-----------------------------|--|
| <b>Nova Group GBC</b><br>442 South Main St<br>Suite # 7<br>Davidson, NC 28036 |  |            |   | <b>Phone</b> (704) 258-5196<br><b>Fax</b><br><b>Website</b> <a href="https://www.novagroupgbc.com/">https://www.novagroupgbc.com/</a> |                                      | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |                             |  |
| Compliance Testing and Monitoring   |  |            |   |   |                                      | UST Equipment Service Contractors   |  |                             |  |
| Automatic Line Leak Detector Testing:   |  | No         | Overfill Prevention Equipment Operability Check:  |   | No                                   | Dispenser Meter Repair/Calibration:   |  | No                          |  |
| Containment Sump Testing:   |  | No         | Statistical Inventory Reconciliation Services:    |   | No                                   | Leak Detection Equipment Installation Servicing:  |  | No                          |  |
| Corrosion Protection Design Experts:  |  | No         | Spill Prevention Equipment Testing:               |   | No                                   | Spill Bucket Installation Repair:   |  | No                          |  |
| Corrosion Protection System Repairs:  |  | No         | Tank Tightness Testing:                           |   | No                                   | UST Equipment Installation - Other:   |  | No                          |  |
| Corrosion Protection System Testing:  |  | No         | UST Internal Inspections (Integrity Assessments): |   | No                                   | UST Equipment Repair:   |  | No                          |  |
| Leak Detection Equipment Operability Check:                                   |  | No         | UST Internal Lining Inspections:                  |   | No                                   | UST System Installation - Complete Systems:   |  | No                          |  |
| Leak Detection Monitoring Services:   |  | No         | Other:  |   | Environmental compliance inspections | UST Piping/Sump Installation:   |  | No                          |  |
| Line Tightness Testing:   |  | No         |   |   |                                      | UST System Removal:   |  | No                          |  |
| Environmental Service Firms   |  |            |   |   |                                      | Other:  |  |                             |  |
| Emergency Cleanup - Spill/Release:  |  | No         | UST Compliance Consultants:                       |   | <u>Yes</u>                           |   |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:                               |  | <u>Yes</u> | UST Equipment Verification:                       |   | No                                   |   |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                           |  | <u>Yes</u> | Waste Disposal and Treatment:                     |   | No                                   |   |  |                             |  |
| Oil and Solvent Recycling:  |  | No         | Other:  |   | due diligence                        |   |  |                             |  |
| Soil and Water Testing Lab:   |  | No         |   |   |                                      |   |  |                             |  |



## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     | Listing Submitted                                     |    | 11/19/2020  |  | Area of state conducts work |  |
|---|-----|---|----|---|--|-----------------------------|--|
| Paragon Environmental Consultants, Inc.<br>P. O. Box 157<br>Thomasville, NC 27361 |     | Phone (336) 669-6037<br>Fax (336) 476-7708<br>Website |    | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): No<br>Mountains (West of I-77): No |  |                             |  |
| Compliance Testing and Monitoring   |     |   |    | UST Equipment Service Contractors   |  |                             |  |
| Automatic Line Leak Detector Testing:   | No  | Overfill Prevention Equipment Operability Check:      | No | Dispenser Meter Repair/Calibration:   |  | No                          |  |
| Containment Sump Testing:   | No  | Statistical Inventory Reconciliation Services:        | No | Leak Detection Equipment Installation Servicing:  |  | No                          |  |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:                   | No | Spill Bucket Installation Repair:   |  | No                          |  |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:                               | No | UST Equipment Installation - Other:   |  | No                          |  |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments):     | No | UST Equipment Repair:   |  | No                          |  |
| Leak Detection Equipment Operability Check:                                       | No  | UST Internal Lining Inspections:                      | No | UST System Installation - Complete Systems:   |  | No                          |  |
| Leak Detection Monitoring Services:   | No  | Other:  |    | UST Piping/Sump Installation:   |  | No                          |  |
| Line Tightness Testing:   | No  |   |    | UST System Removal:   |  | No                          |  |
| Environmental Service Firms   |     |   |    | Other:  |  |                             |  |
| Emergency Cleanup - Spill/Release:  | Yes | UST Compliance Consultants:                           | No |   |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:                                   | Yes | UST Equipment Verification:                           | No |   |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                               | Yes | Waste Disposal and Treatment:                         | No |   |  |                             |  |
| Oil and Solvent Recycling:  | No  | Other:  |    |   |  |                             |  |
| Soil and Water Testing Lab:   | No  |   |    |   |  |                             |  |

| Company  |     | Listing Submitted   |    | 7/30/2020  |  | Area of state conducts work   |    |
|--|-----|---|----|--|--|---|----|
| Peak Hydrogeologic, PLLC<br>470 Hogback Mountain Road<br>Tryon, NC 28782 |     | Phone (828) 817-5209<br><br>Fax<br><br>Website <a href="http://www.peakhydrogeologic.com">www.peakhydrogeologic.com</a> |    |  |  | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |    |
| Compliance Testing and Monitoring  |     |   |    | UST Equipment Service Contractors                |  |   |    |
| Automatic Line Leak Detector Testing:                                    | No  | Overfill Prevention Equipment Operability Check:  | No | Dispenser Meter Repair/Calibration:              |  |   | No |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:  | No | Leak Detection Equipment Installation Servicing: |  |   | No |
| Corrosion Protection Design Experts:                                     | No  | Spill Prevention Equipment Testing:   | No | Spill Bucket Installation Repair:                |  |   | No |
| Corrosion Protection System Repairs:                                     | No  | Tank Tightness Testing:   | No | UST Equipment Installation - Other:              |  |   | No |
| Corrosion Protection System Testing:                                     | No  | UST Internal Inspections (Integrity Assessments):   | No | UST Equipment Repair:                            |  |   | No |
| Leak Detection Equipment Operability Check:                              | No  | UST Internal Lining Inspections:  | No | UST System Installation - Complete Systems:      |  |   | No |
| Leak Detection Monitoring Services:                                      | No  | Other:  |    | UST Piping/Sump Installation:                    |  |   | No |
| Line Tightness Testing:  | No  |   |    | UST System Removal:                              |  |   | No |
| Environmental Service Firms  |     |   |    | Other:   |  |   |    |
| Emergency Cleanup - Spill/Release:                                       | No  | UST Compliance Consultants:   | No |  |  |   |    |
| Environmental Engineer/Geologist - Site Checks:                          | Yes | UST Equipment Verification:   | No |  |  |   |    |
| Environmental Engineer/Geologist Soil and GW Cleanu                      | Yes | Waste Disposal and Treatment:   | No |  |  |   |    |
| Oil and Solvent Recycling:   | No  | Other:  |    |  |  |   |    |
| Soil and Water Testing Lab:  | No  |   |    |  |  |   |    |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     |   | Listing Submitted  |  | 12/30/2021 | Area of state conducts work   |     |
|--|-----|---|--|--|------------|---|-----|
| Petroleum Equipment and Service, Inc.<br>4125 Sinclair Street<br>PO Box 1949<br>Denver, NC 28037 |     |   | Phone (704) 335-8801<br>Fax (704) 342-1672<br>Website <a href="http://www.petroleumequipment.net">www.petroleumequipment.net</a> |  |            | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |     |
| Compliance Testing and Monitoring  |     |   |  |  |            | UST Equipment Service Contractors   |     |
| Automatic Line Leak Detector Testing:  | Yes | Overfill Prevention Equipment Operability Check:  | Yes  | Dispenser Meter Repair/Calibration:              |            |   | Yes |
| Containment Sump Testing:  | Yes | Statistical Inventory Reconciliation Services:    | No   | Leak Detection Equipment Installation Servicing: |            |   | Yes |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:               | Yes  | Spill Bucket Installation Repair:                |            |   | Yes |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:                           | Yes  | UST Equipment Installation - Other:              |            |   | Yes |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments): | Yes  | UST Equipment Repair:                            |            |   | Yes |
| Leak Detection Equipment Operability Check:  | Yes | UST Internal Lining Inspections:                  | Yes  | UST System Installation - Complete Systems:      |            |   | Yes |
| Leak Detection Monitoring Services:  | Yes | Other:  |  | UST Piping/Sump Installation:                    |            |   | Yes |
| Line Tightness Testing:  | Yes |   |  | UST System Removal:                              |            |   | Yes |
| Environmental Service Firms  |     |   |  |  |            | Other:  |     |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                       | No   |  |            |   |     |
| Environmental Engineer/Geologist - Site Checks:  | No  | UST Equipment Verification:                       | No   |  |            |   |     |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No  | Waste Disposal and Treatment:                     | Yes  |  |            |   |     |
| Oil and Solvent Recycling:   | No  | Other:  |  |  |            |   |     |
| Soil and Water Testing Lab:  | No  |   |  |  |            |   |     |

| Company   |     |   | Listing Submitted  |  | 5/14/2021 | Area of state conducts work   |     |
|---|-----|---|--|--|-----------|---|-----|
| Petroleum Solutions Inc.<br>3012 Whitehart Ln.<br>819 Purser Drive<br>Raleigh, NC 27606 |     |   | Phone (919) 605-1979<br>Fax (919) 773-1704<br>Website <a href="http://www.petroleumsolutionsinc.net">www.petroleumsolutionsinc.net</a> |  |           | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): No |     |
| Compliance Testing and Monitoring   |     |   |  |  |           | UST Equipment Service Contractors   |     |
| Automatic Line Leak Detector Testing:   | No  | Overfill Prevention Equipment Operability Check:  | Yes  | Dispenser Meter Repair/Calibration:              |           |   | No  |
| Containment Sump Testing:   | Yes | Statistical Inventory Reconciliation Services:    | No   | Leak Detection Equipment Installation Servicing: |           |   | No  |
| Corrosion Protection Design Experts:  | No  | Spill Prevention Equipment Testing:               | Yes  | Spill Bucket Installation Repair:                |           |   | Yes |
| Corrosion Protection System Repairs:  | No  | Tank Tightness Testing:                           | No   | UST Equipment Installation - Other:              |           |   | Yes |
| Corrosion Protection System Testing:  | No  | UST Internal Inspections (Integrity Assessments): | No   | UST Equipment Repair:                            |           |   | Yes |
| Leak Detection Equipment Operability Check:   | No  | UST Internal Lining Inspections:                  | No   | UST System Installation - Complete Systems:      |           |   | Yes |
| Leak Detection Monitoring Services:   | No  | Other:  |  | UST Piping/Sump Installation:                    |           |   | Yes |
| Line Tightness Testing:   | No  |   |  | UST System Removal:                              |           |   | Yes |
| Environmental Service Firms   |     |   |  |  |           | Other:  |     |
| Emergency Cleanup - Spill/Release:  | No  | UST Compliance Consultants:                       | No   |  |           |   |     |
| Environmental Engineer/Geologist - Site Checks:   | No  | UST Equipment Verification:                       | Yes  |  |           |   |     |
| Environmental Engineer/Geologist Soil and GW Cleanu                                     | No  | Waste Disposal and Treatment:                     | No   |  |           |   |     |
| Oil and Solvent Recycling:  | No  | Other:  |  |  |           |   |     |
| Soil and Water Testing Lab:   | No  |   |  |  |           |   |     |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |            |   | Listing Submitted  |  | 3/31/2022                         | Area of state conducts work   |  |
|---|------------|---|--|--|-----------------------------------|---|--|
| <b>Petroleum Tec</b><br>5420 Powerhouse Ct<br>Concord, NC 28027 |            |   | <b>Phone</b> (980) 781-1000<br><b>Fax</b><br><b>Website</b> <a href="http://www.petroileumtec.com">www.petroileumtec.com</a> |  |                                   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring                               |            |   |  |  | UST Equipment Service Contractors |   |  |
| Automatic Line Leak Detector Testing:                           | No         | Overfill Prevention Equipment Operability Check:  | No   | Dispenser Meter Repair/Calibration:              | No                                |   |  |
| Containment Sump Testing:                                       | No         | Statistical Iventory Reconciliation Services:     | No   | Leak Detection Equipment Installation Servicing: | No                                |   |  |
| Corrosion Protection Design Experts:                            | No         | Spill Prevention Equipment Testing:               | No   | Spill Bucket Installation Repair:                | No                                |   |  |
| Corrosion Protection System Repairs:                            | No         | Tank Tightness Testing:                           | No   | UST Equipment Installation - Other:              | No                                |   |  |
| Corrosion Protection System Testing:                            | No         | UST Internal Inspections (Integrity Assessments): | No   | UST Equipment Repair:                            | No                                |   |  |
| Leak Detection Equipment Operability Check:                     | No         | UST Internal Lining Inspections:                  | No   | UST System Installation - Complete Systems:      | No                                |   |  |
| Leak Detection Monitoring Services:                             | No         | Other:  | Tank Cleaning  | UST Piping/Sump Installation:                    | No                                |   |  |
| Line Tightness Testing:   | No         |   |  | UST System Removal:                              | No                                |   |  |
| Environmental Service Firms                                     |            |   |  |  | Other: Tank Cleaning              |   |  |
| Emergency Cleanup - Spill/Release:                              | <u>Yes</u> | UST Compliance Consultants:                       | No   |  |                                   |   |  |
| Environmental Engineer/Geologist - Site Checks:                 | No         | UST Equipment Verification:                       | No   |  |                                   |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu             | No         | Waste Disposal and Treatment:                     | <u>Yes</u>   |  |                                   |   |  |
| Oil and Solvent Recycling:                                      | No         | Other:  | Tank Cleaning  |  |                                   |   |  |
| Soil and Water Testing Lab:                                     | No         |   |  |  |                                   |   |  |

| Company  |            |   | Listing Submitted   |  | 7/30/2020                         | Area of state conducts work   |  |
|--|------------|---|---|--|-----------------------------------|---|--|
| <b>Pilot Geological, PLLC</b><br>743 Park Lawn Court<br>PO 128<br>Kernersville, NC 27285 |            |   | <b>Phone</b> (336) 310-4527<br><b>Fax</b> (336) 310-4527<br><b>Website</b> <a href="http://www.pilotenviro.com">www.pilotenviro.com</a> |  |                                   | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring  |            |   |   |  | UST Equipment Service Contractors |   |  |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              | No                                |   |  |
| Containment Sump Testing:  | No         | Statistical Iventory Reconciliation Services:     | No  | Leak Detection Equipment Installation Servicing: | No                                |   |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:               | No  | Spill Bucket Installation Repair:                | No                                |   |  |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:                           | No  | UST Equipment Installation - Other:              | No                                |   |  |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair:                            | No                                |   |  |
| Leak Detection Equipment Operability Check:  | No         | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems:      | No                                |   |  |
| Leak Detection Monitoring Services:  | No         | Other:  |   | UST Piping/Sump Installation:                    | No                                |   |  |
| Line Tightness Testing:  | No         |   |   | UST System Removal:                              | <u>Yes</u>                        |   |  |
| Environmental Service Firms  |            |   |   |  | Other:                            |   |  |
| Emergency Cleanup - Spill/Release:   | <u>Yes</u> | UST Compliance Consultants:                       | <u>Yes</u>  |  |                                   |   |  |
| Environmental Engineer/Geologist - Site Checks:  | <u>Yes</u> | UST Equipment Verification:                       | <u>Yes</u>  |  |                                   |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                                      | <u>Yes</u> | Waste Disposal and Treatment:                     | <u>Yes</u>  |  |                                   |   |  |
| Oil and Solvent Recycling:   | No         | Other:  |   |  |                                   |   |  |
| Soil and Water Testing Lab:  | No         |   |   |  |                                   |   |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |            | Listing Submitted   |                      | 11/8/2019  |   | Area of state conducts work |  |
|--|------------|---|----------------------|--|---|-----------------------------|--|
| Practical Environmental Solutions, PC<br>5634 Harvest Grove Lane<br>Wilmington, NC 28409 |            | Phone (910) 790-8265<br><br>Fax<br><br>Website <a href="http://www.oil-tank.com">www.oil-tank.com</a> |                      |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): No |                             |  |
| Compliance Testing and Monitoring  |            |   |                      | UST Equipment Service Contractors                |   |                             |  |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:  | No                   | Dispenser Meter Repair/Calibration:              | No  |                             |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:  | No                   | Leak Detection Equipment Installation Servicing: | No  |                             |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:   | No                   | Spill Bucket Installation Repair:                | No  |                             |  |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:   | No                   | UST Equipment Installation - Other:              | No  |                             |  |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments):   | No                   | UST Equipment Repair:                            | No  |                             |  |
| Leak Detection Equipment Operability Check:  | No         | UST Internal Lining Inspections:  | No                   | UST System Installation - Complete Systems:      | No  |                             |  |
| Leak Detection Monitoring Services:  | No         | Other:  |                      | UST Piping/Sump Installation:                    | No  |                             |  |
| Line Tightness Testing:  | No         |   |                      | UST System Removal:                              | <u>Yes</u>  |                             |  |
| Environmental Service Firms  |            |   |                      | Other:   |   |                             |  |
| Emergency Cleanup - Spill/Release:   | <u>Yes</u> | UST Compliance Consultants:   | <u>Yes</u>           |  |   |                             |  |
| Environmental Engineer/Geologist - Site Checks:  | <u>Yes</u> | UST Equipment Verification:   | No                   |  |   |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                                      | <u>Yes</u> | Waste Disposal and Treatment:   | No                   |  |   |                             |  |
| Oil and Solvent Recycling:   | No         | Other:  | Oil Tank Evaluations |  |   |                             |  |
| Soil and Water Testing Lab:  | <u>Yes</u> |   |                      |  |   |                             |  |

| Company  |            | Listing Submitted   |    | 10/12/2022                                       |  | Area of state conducts work   |  |
|--|------------|---|----|--|--|---|--|
| Practical Environmental Solutions. PC<br>5634 Harvest Grove Ln<br>Wilmington, NC 28409 |            | Phone (910) 790-8265<br><br>Fax<br><br>Website <a href="http://www.oil-tank.com">www.oil-tank.com</a> |    |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): No |  |
| Compliance Testing and Monitoring  |            |   |    | UST Equipment Service Contractors                |  |   |  |
| Automatic Line Leak Detector Testing:  | No         | Overfill Prevention Equipment Operability Check:  | No | Dispenser Meter Repair/Calibration:              |  | No  |  |
| Containment Sump Testing:  | No         | Statistical Inventory Reconciliation Services:  | No | Leak Detection Equipment Installation Servicing: |  | No  |  |
| Corrosion Protection Design Experts:   | No         | Spill Prevention Equipment Testing:   | No | Spill Bucket Installation Repair:                |  | No  |  |
| Corrosion Protection System Repairs:   | No         | Tank Tightness Testing:   | No | UST Equipment Installation - Other:              |  | No  |  |
| Corrosion Protection System Testing:   | No         | UST Internal Inspections (Integrity Assessments):   | No | UST Equipment Repair:                            |  | No  |  |
| Leak Detection Equipment Operability Check:  | No         | UST Internal Lining Inspections:  | No | UST System Installation - Complete Systems:      |  | No  |  |
| Leak Detection Monitoring Services:  | No         | Other:  |    | UST Piping/Sump Installation:                    |  | No  |  |
| Line Tightness Testing:  | No         |   |    | UST System Removal:                              |  | <u>Yes</u>  |  |
| Environmental Service Firms  |            |   |    | Other:   |  |   |  |
| Emergency Cleanup - Spill/Release:   | No         | UST Compliance Consultants:   | No |  |  |   |  |
| Environmental Engineer/Geologist - Site Checks:  | <u>Yes</u> | UST Equipment Verification:   | No |  |  |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                                    | <u>Yes</u> | Waste Disposal and Treatment:   | No |  |  |   |  |
| Oil and Solvent Recycling:   | No         | Other:  |    |  |  |   |  |
| Soil and Water Testing Lab:  | <u>Yes</u> |   |    |  |  |   |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |     |   | Listing Submitted  | 12/30/2021                                       | Area of state conducts work  |  |
|---|-----|---|--|--|--|--|
| Precision Tank Service<br>737 Zimmer Road<br>Fort Mill , SC 29707 |     |   | Phone (704) 892-8600<br>Fax (704) 892-8711<br>Website <a href="http://www.precisiontankservice.com">www.precisiontankservice.com</a> |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring                                 |     |   |  |  | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:                             | Yes | Overfill Prevention Equipment Operability Check:  | Yes  | Dispenser Meter Repair/Calibration:              | No   |  |
| Containment Sump Testing:   | Yes | Statistical Inventory Reconciliation Services:    | No   | Leak Detection Equipment Installation Servicing: | No   |  |
| Corrosion Protection Design Experts:                              | No  | Spill Prevention Equipment Testing:               | Yes  | Spill Bucket Installation Repair:                | No   |  |
| Corrosion Protection System Repairs:                              | No  | Tank Tightness Testing:                           | Yes  | UST Equipment Installation - Other:              | No   |  |
| Corrosion Protection System Testing:                              | Yes | UST Internal Inspections (Integrity Assessments): | No   | UST Equipment Repair:                            | Yes  |  |
| Leak Detection Equipment Operability Check:                       | Yes | UST Internal Lining Inspections:                  | No   | UST System Installation - Complete Systems:      | No   |  |
| Leak Detection Monitoring Services:                               | Yes | Other:  |  | UST Piping/Sump Installation:                    | No   |  |
| Line Tightness Testing:   | Yes |   |  | UST System Removal:                              | No   |  |
| Environmental Service Firms                                       |     |   |  |  | Other:   |  |
| Emergency Cleanup - Spill/Release:                                | No  | UST Compliance Consultants:                       | Yes  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:                   | No  | UST Equipment Verification:                       | No   |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu               | No  | Waste Disposal and Treatment:                     | No   |  |  |  |
| Oil and Solvent Recycling:  | No  | Other:  |  |  |  |  |
| Soil and Water Testing Lab:                                       | No  |   |  |  |  |  |

| Company  |     |   | Listing Submitted   | 2/24/2020  | Area of state conducts work  |  |
|--|-----|---|---|--|--|--|
| Professional Service Industries, Inc.<br>5021 W W.T. Harris Blvd.<br>Charlotte, NC 28269 |     |   | Phone (704) 598-2234<br>Fax (704) 598-2236<br>Website <a href="http://www.intertek.com/building">http://www.intertek.com/building</a> |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |
| Compliance Testing and Monitoring  |     |   |   |  | UST Equipment Service Contractors  |  |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              | No   |  |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:    | No  | Leak Detection Equipment Installation Servicing: | No   |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:               | No  | Spill Bucket Installation Repair:                | No   |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:                           | No  | UST Equipment Installation - Other:              | No   |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair:                            | No   |  |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems:      | No   |  |
| Leak Detection Monitoring Services:  | No  | Other:  |   | UST Piping/Sump Installation:                    | No   |  |
| Line Tightness Testing:  | No  |   |   | UST System Removal:                              | No   |  |
| Environmental Service Firms  |     |   |   |  | Other:   |  |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                       | No  |  |  |  |
| Environmental Engineer/Geologist - Site Checks:  | Yes | UST Equipment Verification:                       | No  |  |  |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                                      | Yes | Waste Disposal and Treatment:                     | No  |  |  |  |
| Oil and Solvent Recycling:   | No  | Other:  |   |  |  |  |
| Soil and Water Testing Lab:  | No  |   |   |  |  |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |            |   | Listing Submitted   |  | 1/3/2022  |  | Area of state conducts work |  |
|---|------------|---|---|--|---|--|-----------------------------|--|
| <b>Pyramid Environmental &amp; Engineering, PC</b><br>503 Industrial Avenue<br>Greensboro, NC 27406 |            |   | <b>Phone</b> (336) 335-3174<br><b>Fax</b> (336) 691-0648<br><b>Website</b> <a href="http://www.PyramidEnvironmental.com">www.PyramidEnvironmental.com</a> |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |                             |  |
| Compliance Testing and Monitoring   |            |   |   |  | UST Equipment Service Contractors   |  |                             |  |
| Automatic Line Leak Detector Testing:   | No         | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              | No  |  |                             |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:    | No  | Leak Detection Equipment Installation Servicing: | No  |  |                             |  |
| Corrosion Protection Design Experts:  | No         | Spill Prevention Equipment Testing:               | No  | Spill Bucket Installation Repair:                | No  |  |                             |  |
| Corrosion Protection System Repairs:  | No         | Tank Tightness Testing:                           | No  | UST Equipment Installation - Other:              | No  |  |                             |  |
| Corrosion Protection System Testing:  | No         | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair:                            | No  |  |                             |  |
| Leak Detection Equipment Operability Check:   | No         | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems:      | No  |  |                             |  |
| Leak Detection Monitoring Services:   | No         | Other:  |   | UST Piping/Sump Installation:                    | No  |  |                             |  |
| Line Tightness Testing:   | No         |   |   | UST System Removal:                              | <u>Yes</u>  |  |                             |  |
| Environmental Service Firms   |            |   |   |  | Other:  |  |                             |  |
| Emergency Cleanup - Spill/Release:  | <u>Yes</u> | UST Compliance Consultants:                       | <u>Yes</u>  |  |   |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:   | <u>Yes</u> | UST Equipment Verification:                       | No  |  |   |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | <u>Yes</u> | Waste Disposal and Treatment:                     | <u>Yes</u>  |  |   |  |                             |  |
| Oil and Solvent Recycling:  | No         | Other:  |   |  |   |  |                             |  |
| Soil and Water Testing Lab:   | <u>Yes</u> |   |   |  |   |  |                             |  |

| Company   |            |   | Listing Submitted  |  | 9/14/2020   |  | Area of state conducts work |  |
|---|------------|---|--|--|---|--|-----------------------------|--|
| <b>Schnabel Engineering Sourh, P.C.</b><br>244 Princess Street, Suite 205<br>Wilmington, NC 28401 |            |   | <b>Phone</b> (910) 769-1621<br><b>Fax</b><br><b>Website</b> <a href="http://www.schnabel-eng.com">www.schnabel-eng.com</a> |  | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |                             |  |
| Compliance Testing and Monitoring   |            |   |  |  | UST Equipment Service Contractors   |  |                             |  |
| Automatic Line Leak Detector Testing:   | No         | Overfill Prevention Equipment Operability Check:  | No   | Dispenser Meter Repair/Calibration:              | No  |  |                             |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:    | No   | Leak Detection Equipment Installation Servicing: | No  |  |                             |  |
| Corrosion Protection Design Experts:  | No         | Spill Prevention Equipment Testing:               | No   | Spill Bucket Installation Repair:                | No  |  |                             |  |
| Corrosion Protection System Repairs:  | No         | Tank Tightness Testing:                           | No   | UST Equipment Installation - Other:              | No  |  |                             |  |
| Corrosion Protection System Testing:  | No         | UST Internal Inspections (Integrity Assessments): | No   | UST Equipment Repair:                            | No  |  |                             |  |
| Leak Detection Equipment Operability Check:   | No         | UST Internal Lining Inspections:                  | No   | UST System Installation - Complete Systems:      | No  |  |                             |  |
| Leak Detection Monitoring Services:   | No         | Other:  |  | UST Piping/Sump Installation:                    | No  |  |                             |  |
| Line Tightness Testing:   | No         |   |  | UST System Removal:                              | <u>Yes</u>  |  |                             |  |
| Environmental Service Firms   |            |   |  |  | Other:  |  |                             |  |
| Emergency Cleanup - Spill/Release:  | <u>Yes</u> | UST Compliance Consultants:                       | <u>Yes</u>   |  |   |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:   | <u>Yes</u> | UST Equipment Verification:                       | No   |  |   |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu   | <u>Yes</u> | Waste Disposal and Treatment:                     | <u>Yes</u>   |  |   |  |                             |  |
| Oil and Solvent Recycling:  | No         | Other:  |  |  |   |  |                             |  |
| Soil and Water Testing Lab:   | <u>Yes</u> |   |  |  |   |  |                             |  |



## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     | Listing Submitted   |                  | 12/30/2021                                       |  | Area of state conducts work  |    |
|--|-----|---|------------------|--|--|--|----|
| Sensible Solutions Environmental, P. C.<br>P. O. Box 3074<br>Chapel Hill, NC 27515 |     | Phone (336) 263-0965<br><br>Fax<br><br>Website <a href="http://www.sensible-solutions-environmental.com">www.sensible-solutions-environmental.com</a> |                  |  |  | Coastal (East of I-95): No<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): No |    |
| Compliance Testing and Monitoring  |     |   |                  | UST Equipment Service Contractors                |  |  |    |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:  | No               | Dispenser Meter Repair/Calibration:              |  |  | No |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:  | No               | Leak Detection Equipment Installation Servicing: |  |  | No |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:   | No               | Spill Bucket Installation Repair:                |  |  | No |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:   | No               | UST Equipment Installation - Other:              |  |  | No |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):   | No               | UST Equipment Repair:                            |  |  | No |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:  | No               | UST System Installation - Complete Systems:      |  |  | No |
| Leak Detection Monitoring Services:  | No  | Other:  |                  | UST Piping/Sump Installation:                    |  |  | No |
| Line Tightness Testing:  | No  |   |                  | UST System Removal:                              |  |  | No |
| Environmental Service Firms  |     |   |                  | Other:   |  |  |    |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:   | No               |  |  |  |    |
| Environmental Engineer/Geologist - Site Checks:                                    | Yes | UST Equipment Verification:   | No               |  |  |  |    |
| Environmental Engineer/Geologist Soil and GW Cleanu                                | Yes | Waste Disposal and Treatment:   | No               |  |  |  |    |
| Oil and Solvent Recycling:   | No  | Other:  | Residential USTs |  |  |  |    |
| Soil and Water Testing Lab:  | No  |   |                  |  |  |  |    |

| Company  |     | Listing Submitted  |     | 12/12/2019                                       |  | Area of state conducts work  |    |
|--|-----|--|-----|--|--|--|----|
| Shield Engineering, Inc.<br>4301 Taggart Creek Road<br>Charlotte, NC 28208 |     | Phone (704) 394-6913<br><br>Fax (704) 394-6968<br><br>Website <a href="http://www.shieldengineering.com">www.shieldengineering.com</a> |     |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |    |
| Compliance Testing and Monitoring  |     |  |     | UST Equipment Service Contractors                |  |  |    |
| Automatic Line Leak Detector Testing:                                      | No  | Overfill Prevention Equipment Operability Check:   | No  | Dispenser Meter Repair/Calibration:              |  |  | No |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:   | No  | Leak Detection Equipment Installation Servicing: |  |  | No |
| Corrosion Protection Design Experts:                                       | No  | Spill Prevention Equipment Testing:  | No  | Spill Bucket Installation Repair:                |  |  | No |
| Corrosion Protection System Repairs:                                       | No  | Tank Tightness Testing:  | No  | UST Equipment Installation - Other:              |  |  | No |
| Corrosion Protection System Testing:                                       | No  | UST Internal Inspections (Integrity Assessments):  | No  | UST Equipment Repair:                            |  |  | No |
| Leak Detection Equipment Operability Check:                                | No  | UST Internal Lining Inspections:   | No  | UST System Installation - Complete Systems:      |  |  | No |
| Leak Detection Monitoring Services:  | No  | Other:   |     | UST Piping/Sump Installation:                    |  |  | No |
| Line Tightness Testing:  | No  |  |     | UST System Removal:                              |  |  | No |
| Environmental Service Firms  |     |  |     | Other:   |  |  |    |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:  | Yes |  |  |  |    |
| Environmental Engineer/Geologist - Site Checks:                            | Yes | UST Equipment Verification:  | No  |  |  |  |    |
| Environmental Engineer/Geologist Soil and GW Cleanu                        | Yes | Waste Disposal and Treatment:  | Yes |  |  |  |    |
| Oil and Solvent Recycling:   | No  | Other:   |     |  |  |  |    |
| Soil and Water Testing Lab:  | Yes |  |     |  |  |  |    |

| Company  |     | Listing Submitted                                 |                           | 12/12/2019                                       |  | Area of state conducts work |     |
|--|-----|---|---------------------------|--|--|-----------------------------|-----|
| Shield Engineering, Inc.<br>4301 Taggart Creek Road<br>Charlotte, NC 28208 |     | Phone   | (704) 394-6913            |  | Coastal (East of I-95):                  |                             | Yes |
|  |     | Fax   | (704) 394-6968            |  | Central (West of I-95 and East of I-77): |                             | Yes |
|  |     | Website   | www.shieldengineering.com |  | Mountains (West of I-77):                |                             | Yes |
| Compliance Testing and Monitoring  |     |   |                           | UST Equipment Service Contractors                |  |                             |     |
| Automatic Line Leak Detector Testing:                                      | No  | Overfill Prevention Equipment Operability Check:  | No                        | Dispenser Meter Repair/Calibration:              |  | No                          |     |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:    | No                        | Leak Detection Equipment Installation Servicing: |  | No                          |     |
| Corrosion Protection Design Experts:                                       | No  | Spill Prevention Equipment Testing:               | No                        | Spill Bucket Installation Repair:                |  | No                          |     |
| Corrosion Protection System Repairs:                                       | No  | Tank Tightness Testing:                           | No                        | UST Equipment Installation - Other:              |  | No                          |     |
| Corrosion Protection System Testing:                                       | No  | UST Internal Inspections (Integrity Assessments): | No                        | UST Equipment Repair:                            |  | No                          |     |
| Leak Detection Equipment Operability Check:                                | No  | UST Internal Lining Inspections:                  | No                        | UST System Installation - Complete Systems:      |  | No                          |     |
| Leak Detection Monitoring Services:  | No  | Other:  |                           | UST Piping/Sump Installation:                    |  | No                          |     |
| Line Tightness Testing:  | No  |   |                           | UST System Removal:                              |  | No                          |     |
| Environmental Service Firms  |     |   |                           | Other:   |  |                             |     |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:                       | Yes                       |  |  |                             |     |
| Environmental Engineer/Geologist - Site Checks:                            | Yes | UST Equipment Verification:                       | No                        |  |  |                             |     |
| Environmental Engineer/Geologist Soil and GW Cleanu                        | Yes | Waste Disposal and Treatment:                     | Yes                       |  |  |                             |     |
| Oil and Solvent Recycling:   | No  | Other:  |                           |  |  |                             |     |
| Soil and Water Testing Lab:  | Yes |   |                           |  |  |                             |     |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |            | Listing Submitted   |    | 12/30/2021   |  | Area of state conducts work |  |
|---|------------|---|----|--|--|-----------------------------|--|
| Singleton Environmental, Inc.<br>PO Box 604<br>Fletcher, NC 28732 |            | Phone (828) 508-4510<br><br>Fax<br><br>Website <a href="http://singletonenvironmental.com">singletonenvironmental.com</a> |    | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |                             |  |
| Compliance Testing and Monitoring                                 |            |   |    | UST Equipment Service Contractors  |  |                             |  |
| Automatic Line Leak Detector Testing:                             | No         | Overfill Prevention Equipment Operability Check:  | No | Dispenser Meter Repair/Calibration:  |  | No                          |  |
| Containment Sump Testing:   | No         | Statistical Inventory Reconciliation Services:  | No | Leak Detection Equipment Installation Servicing:   |  | No                          |  |
| Corrosion Protection Design Experts:                              | No         | Spill Prevention Equipment Testing:   | No | Spill Bucket Installation Repair:  |  | No                          |  |
| Corrosion Protection System Repairs:                              | No         | Tank Tightness Testing:   | No | UST Equipment Installation - Other:  |  | No                          |  |
| Corrosion Protection System Testing:                              | No         | UST Internal Inspections (Integrity Assessments):   | No | UST Equipment Repair:  |  | No                          |  |
| Leak Detection Equipment Operability Check:                       | No         | UST Internal Lining Inspections:  | No | UST System Installation - Complete Systems:  |  | No                          |  |
| Leak Detection Monitoring Services:                               | No         | Other:  |    | UST Piping/Sump Installation:  |  | No                          |  |
| Line Tightness Testing:   | No         |   |    | UST System Removal:  |  | No                          |  |
| Environmental Service Firms                                       |            |   |    | Other:   |  |                             |  |
| Emergency Cleanup - Spill/Release:                                | No         | UST Compliance Consultants:   | No |  |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:                   | <u>Yes</u> | UST Equipment Verification:   | No |  |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu               | <u>Yes</u> | Waste Disposal and Treatment:   | No |  |  |                             |  |
| Oil and Solvent Recycling:  | No         | Other:  |    |  |  |                             |  |
| Soil and Water Testing Lab:                                       | No         |   |    |  |  |                             |  |

| Company  |     | Listing Submitted                                 |                       | 6/29/2021 |  | Area of state conducts work |     |
|--|-----|---|-----------------------|-----------|--|-----------------------------|-----|
| SR&R Environmental, Inc.<br>4920 Highway 421 N.<br>Wilmington, NC 28401- |     | Phone   | (910) 763-6274        |           | Coastal (East of I-95):                          |                             | Yes |
|  |     | Fax   | (910) 763-6132        |           | Central (West of I-95 and East of I-77):         |                             | Yes |
|  |     | Website   | www.srrenviro.com     |           | Mountains (West of I-77):                        |                             | No  |
| Compliance Testing and Monitoring  |     |   |                       |           | UST Equipment Service Contractors                |                             |     |
| Automatic Line Leak Detector Testing:                                    | No  | Overfill Prevention Equipment Operability Check:  | No                    |           | Dispenser Meter Repair/Calibration:              | No                          |     |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:    | No                    |           | Leak Detection Equipment Installation Servicing: | No                          |     |
| Corrosion Protection Design Experts:                                     | No  | Spill Prevention Equipment Testing:               | No                    |           | Spill Bucket Installation Repair:                | No                          |     |
| Corrosion Protection System Repairs:                                     | No  | Tank Tightness Testing:                           | No                    |           | UST Equipment Installation - Other:              | No                          |     |
| Corrosion Protection System Testing:                                     | No  | UST Internal Inspections (Integrity Assessments): | No                    |           | UST Equipment Repair:                            | No                          |     |
| Leak Detection Equipment Operability Check:                              | No  | UST Internal Lining Inspections:                  | No                    |           | UST System Installation - Complete Systems:      | No                          |     |
| Leak Detection Monitoring Services:                                      | No  | Other:  |                       |           | UST Piping/Sump Installation:                    | No                          |     |
| Line Tightness Testing:  | No  |   |                       |           | UST System Removal:                              | Yes                         |     |
| Environmental Service Firms  |     |   |                       |           | Other:   |                             |     |
| Emergency Cleanup - Spill/Release:                                       | Yes | UST Compliance Consultants:                       | No                    |           |  |                             |     |
| Environmental Engineer/Geologist - Site Checks:                          | No  | UST Equipment Verification:                       | No                    |           |  |                             |     |
| Environmental Engineer/Geologist Soil and GW Cleanu                      | No  | Waste Disposal and Treatment:                     | Yes                   |           |  |                             |     |
| Oil and Solvent Recycling:   | Yes | Other:  | Vacuum Truck Services |           |  |                             |     |
| Soil and Water Testing Lab:  | No  |   |                       |           |  |                             |     |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     | Listing Submitted  |     | 12/30/2021                                       |  | Area of state conducts work  |    |
|--|-----|--|-----|--|--|--|----|
| Terraquest Environmental Consultants, P.C.<br>100 E. Ruffin Street<br>Mebane, NC 27302 |     | Phone (919) 563-9091<br>Fax (919) 563-9095<br>Website <a href="http://www.terraquestpc.com">www.terraquestpc.com</a> |     |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |    |
| Compliance Testing and Monitoring  |     |  |     | UST Equipment Service Contractors                |  |  |    |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:   | No  | Dispenser Meter Repair/Calibration:              |  |  | No |
| Containment Sump Testing:  | Yes | Statistical Inventory Reconciliation Services:   | No  | Leak Detection Equipment Installation Servicing: |  |  | No |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:  | No  | Spill Bucket Installation Repair:                |  |  | No |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:  | No  | UST Equipment Installation - Other:              |  |  | No |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):  | No  | UST Equipment Repair:                            |  |  | No |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:   | No  | UST System Installation - Complete Systems:      |  |  | No |
| Leak Detection Monitoring Services:  | No  | Other:   |     | UST Piping/Sump Installation:                    |  |  | No |
| Line Tightness Testing:  | No  |  |     | UST System Removal:                              |  |  | No |
| Environmental Service Firms  |     |  |     | Other:   |  |  |    |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:  | No  |  |  |  |    |
| Environmental Engineer/Geologist - Site Checks:  | Yes | UST Equipment Verification:  | No  |  |  |  |    |
| Environmental Engineer/Geologist Soil and GW Cleanu                                    | Yes | Waste Disposal and Treatment:  | Yes |  |  |  |    |
| Oil and Solvent Recycling:   | No  | Other:   |     |  |  |  |    |
| Soil and Water Testing Lab:  | Yes |  |     |  |  |  |    |

| Company  |     | Listing Submitted   |     | 3/26/2021  |  | Area of state conducts work  |    |
|--|-----|---|-----|--|--|--|----|
| The Mannik & Smith Group, Inc.<br>4501 New Bern Avenue<br>Suite 130#214<br>Raleigh, NC 27610 |     | Phone (336) 302-9598<br>Fax<br>Website <a href="http://www.MannikSmithGroup.com">www.MannikSmithGroup.com</a> |     |  |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |    |
| Compliance Testing and Monitoring  |     |   |     | UST Equipment Service Contractors                |  |  |    |
| Automatic Line Leak Detector Testing:  | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration:              |  |  | No |
| Containment Sump Testing:  | No  | Statistical Inventory Reconciliation Services:  | No  | Leak Detection Equipment Installation Servicing: |  |  | No |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:   | No  | Spill Bucket Installation Repair:                |  |  | No |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:   | No  | UST Equipment Installation - Other:              |  |  | No |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):   | No  | UST Equipment Repair:                            |  |  | No |
| Leak Detection Equipment Operability Check:  | No  | UST Internal Lining Inspections:  | No  | UST System Installation - Complete Systems:      |  |  | No |
| Leak Detection Monitoring Services:  | No  | Other:  |     | UST Piping/Sump Installation:                    |  |  | No |
| Line Tightness Testing:  | No  |   |     | UST System Removal:                              |  |  | No |
| Environmental Service Firms  |     |   |     | Other:   |  |  |    |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:   | Yes |  |  |  |    |
| Environmental Engineer/Geologist - Site Checks:  | Yes | UST Equipment Verification:   | No  |  |  |  |    |
| Environmental Engineer/Geologist Soil and GW Cleanu  | Yes | Waste Disposal and Treatment:   | Yes |  |  |  |    |
| Oil and Solvent Recycling:   | No  | Other:  |     |  |  |  |    |
| Soil and Water Testing Lab:  | No  |   |     |  |  |  |    |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company   |    |   |  | Listing Submitted                                | 8/12/2020 | Area of state conducts work   |  |
|---|----|---|--|--|-----------|---|--|
| <b>TIMMONS GROUP</b><br>5410 TRINITY ROAD, SUITE 102<br>RALEIGH, NC 27606 |    | <b>Phone</b> (919) 866-4951<br><b>Fax</b><br><b>Website</b> <a href="http://www.timmons.com/">http://www.timmons.com/</a> |  |  |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring   |    |   |  |  |           | UST Equipment Service Contractors   |  |
| Automatic Line Leak Detector Testing:                                     | No | Overfill Prevention Equipment Operability Check:  | No                                       | Dispenser Meter Repair/Calibration:              |           | No  |  |
| Containment Sump Testing:   | No | Statistical Inventory Reconciliation Services:  | No                                       | Leak Detection Equipment Installation Servicing: |           | No  |  |
| Corrosion Protection Design Experts:                                      | No | Spill Prevention Equipment Testing:   | No                                       | Spill Bucket Installation Repair:                |           | No  |  |
| Corrosion Protection System Repairs:                                      | No | Tank Tightness Testing:   | No                                       | UST Equipment Installation - Other:              |           | No  |  |
| Corrosion Protection System Testing:                                      | No | UST Internal Inspections (Integrity Assessments):   | No                                       | UST Equipment Repair:                            |           | No  |  |
| Leak Detection Equipment Operability Check:                               | No | UST Internal Lining Inspections:  | No                                       | UST System Installation - Complete Systems:      |           | No  |  |
| Leak Detection Monitoring Services:                                       | No | Other:  |  | UST Piping/Sump Installation:                    |           | No  |  |
| Line Tightness Testing:   | No |   |  | UST System Removal:                              |           | No  |  |
| Environmental Service Firms   |    |   |  |  |           | Other: SYSTEM DESIGN SERVICES - UST ENGINEERING   |  |
| Emergency Cleanup - Spill/Release:  | No | UST Compliance Consultants:   | Yes                                      |  |           |   |  |
| Environmental Engineer/Geologist - Site Checks:                           | No | UST Equipment Verification:   | No                                       |  |           |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                       | No | Waste Disposal and Treatment:   | No                                       |  |           |   |  |
| Oil and Solvent Recycling:  | No | Other:  | SYSTEM DESIGN SERVICES - UST ENGINEERING |  |           |   |  |
| Soil and Water Testing Lab:   | No |   |  |  |           |   |  |

| Company  |     |  |     | Listing Submitted                                | 8/13/2020 | Area of state conducts work   |  |
|--|-----|--|-----|--|-----------|---|--|
| <b>Unified Services of Texas</b><br>2110 Greenbriar dr.<br>Southlake, TX 76092 |     | <b>Phone</b> (817) 481-9510<br><b>Fax</b><br><b>Website</b> <a href="http://ustfuel.com">ustfuel.com</a> |     |  |           | <b>Coastal (East of I-95):</b> Yes<br><b>Central (West of I-95 and East of I-77):</b> Yes<br><b>Mountains (West of I-77):</b> Yes |  |
| Compliance Testing and Monitoring  |     |  |     |  |           | UST Equipment Service Contractors   |  |
| Automatic Line Leak Detector Testing:  | Yes | Overfill Prevention Equipment Operability Check:   | Yes | Dispenser Meter Repair/Calibration:              |           | No  |  |
| Containment Sump Testing:  | Yes | Statistical Inventory Reconciliation Services:   | Yes | Leak Detection Equipment Installation Servicing: |           | Yes   |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:  | Yes | Spill Bucket Installation Repair:                |           | Yes   |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:  | Yes | UST Equipment Installation - Other:              |           | Yes   |  |
| Corrosion Protection System Testing:   | No  | UST Internal Inspections (Integrity Assessments):  | Yes | UST Equipment Repair:                            |           | Yes   |  |
| Leak Detection Equipment Operability Check:                                    | Yes | UST Internal Lining Inspections:   | Yes | UST System Installation - Complete Systems:      |           | Yes   |  |
| Leak Detection Monitoring Services:  | Yes | Other:   |     | UST Piping/Sump Installation:                    |           | Yes   |  |
| Line Tightness Testing:  | Yes |  |     | UST System Removal:                              |           | Yes   |  |
| Environmental Service Firms  |     |  |     |  |           | Other:  |  |
| Emergency Cleanup - Spill/Release:   | Yes | UST Compliance Consultants:  | Yes |  |           |   |  |
| Environmental Engineer/Geologist - Site Checks:                                | Yes | UST Equipment Verification:  | Yes |  |           |   |  |
| Environmental Engineer/Geologist Soil and GW Cleanu                            | Yes | Waste Disposal and Treatment:  | No  |  |           |   |  |
| Oil and Solvent Recycling:   | Yes | Other:   |     |  |           |   |  |
| Soil and Water Testing Lab:  | No  |  |     |  |           |   |  |

## UST Service Provider List (All) - Environmental Service Firms Only

| Company  |     |   | Listing Submitted  |  | 2/5/2021  |  | Area of state conducts work |  |
|--|-----|---|--|--|---|--|-----------------------------|--|
| Wildco PES<br>440 Harvey Rd<br>497 Lendall Lane Fredericksburg VA 22405<br>Manchester, NH 3103 |     |   | Phone (603) 935-9330<br><br>Fax<br><br>Website WILDCOPES.COM |  | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): No |  |                             |  |
| Compliance Testing and Monitoring  |     |   |  |  | UST Equipment Service Contractors   |  |                             |  |
| Automatic Line Leak Detector Testing:  | Yes | Overfill Prevention Equipment Operability Check:  | Yes  | Dispenser Meter Repair/Calibration: Yes              |   |  |                             |  |
| Containment Sump Testing:  | Yes | Statistical Inventory Reconciliation Services:    | No   | Leak Detection Equipment Installation Servicing: Yes |   |  |                             |  |
| Corrosion Protection Design Experts:   | No  | Spill Prevention Equipment Testing:               | Yes  | Spill Bucket Installation Repair: Yes                |   |  |                             |  |
| Corrosion Protection System Repairs:   | No  | Tank Tightness Testing:                           | Yes  | UST Equipment Installation - Other: Yes              |   |  |                             |  |
| Corrosion Protection System Testing:   | Yes | UST Internal Inspections (Integrity Assessments): | No   | UST Equipment Repair: Yes                            |   |  |                             |  |
| Leak Detection Equipment Operability Check:  | Yes | UST Internal Lining Inspections:                  | No   | UST System Installation - Complete Systems: Yes      |   |  |                             |  |
| Leak Detection Monitoring Services:  | Yes | Other:  |  | UST Piping/Sump Installation: Yes                    |   |  |                             |  |
| Line Tightness Testing:  | Yes |   |  | UST System Removal: Yes                              |   |  |                             |  |
| Environmental Service Firms  |     |   |  |  | Other:  |  |                             |  |
| Emergency Cleanup - Spill/Release:   | No  | UST Compliance Consultants:                       | Yes  |  |   |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:  | No  | UST Equipment Verification:                       | Yes  |  |   |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu  | No  | Waste Disposal and Treatment:                     | No   |  |   |  |                             |  |
| Oil and Solvent Recycling:   | No  | Other:  |  |  |   |  |                             |  |
| Soil and Water Testing Lab:  | No  |   |  |  |   |  |                             |  |

| Company  |     |   | Listing Submitted   |   | 8/13/2020  |  | Area of state conducts work |  |
|--|-----|---|---|---|--|--|-----------------------------|--|
| WithersRavenel, Inc.<br>115 MacKenan Drive<br>Cary, NC 27511 |     |   | Phone (919) 469-3340<br><br>Fax<br><br>Website www.withersravenel.com |   | Coastal (East of I-95): Yes<br>Central (West of I-95 and East of I-77): Yes<br>Mountains (West of I-77): Yes |  |                             |  |
| Compliance Testing and Monitoring                            |     |   |   |   | UST Equipment Service Contractors  |  |                             |  |
| Automatic Line Leak Detector Testing:                        | No  | Overfill Prevention Equipment Operability Check:  | No  | Dispenser Meter Repair/Calibration: No              |  |  |                             |  |
| Containment Sump Testing:                                    | No  | Statistical Inventory Reconciliation Services:    | No  | Leak Detection Equipment Installation Servicing: No |  |  |                             |  |
| Corrosion Protection Design Experts:                         | No  | Spill Prevention Equipment Testing:               | No  | Spill Bucket Installation Repair: No                |  |  |                             |  |
| Corrosion Protection System Repairs:                         | No  | Tank Tightness Testing:                           | No  | UST Equipment Installation - Other: No              |  |  |                             |  |
| Corrosion Protection System Testing:                         | No  | UST Internal Inspections (Integrity Assessments): | No  | UST Equipment Repair: No                            |  |  |                             |  |
| Leak Detection Equipment Operability Check:                  | No  | UST Internal Lining Inspections:                  | No  | UST System Installation - Complete Systems: No      |  |  |                             |  |
| Leak Detection Monitoring Services:                          | No  | Other:  |   | UST Piping/Sump Installation: No                    |  |  |                             |  |
| Line Tightness Testing:                                      | No  |   |   | UST System Removal: Yes                             |  |  |                             |  |
| Environmental Service Firms                                  |     |   |   |   | Other:   |  |                             |  |
| Emergency Cleanup - Spill/Release:                           | Yes | UST Compliance Consultants:                       | Yes   |   |  |  |                             |  |
| Environmental Engineer/Geologist - Site Checks:              | Yes | UST Equipment Verification:                       | No  |   |  |  |                             |  |
| Environmental Engineer/Geologist Soil and GW Cleanu          | Yes | Waste Disposal and Treatment:                     | Yes   |   |  |  |                             |  |
| Oil and Solvent Recycling:                                   | No  | Other:  | Phase I ESAs  |   |  |  |                             |  |
| Soil and Water Testing Lab:                                  | No  |   |   |   |  |  |                             |  |